

EX COPY RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND DEPT.	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-68

<p align="center"><b>SUNDRY NOTICES AND REPORTS ON WELLS</b></p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO RE-ENTER OR PLUG BACK TO A DIFFERENT RESERVOIR. USE IN APPLICATION FOR PERMIT TO DRILL (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		<p>5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/></p> <p>5. State Oil &amp; Gas Lease No. B-7018</p>
<p>6. Name of Operator B. J. Berry Mining Company Box 1800, Midland, Texas 79701</p>		<p>7. Unit Agreement Name</p>
<p>8. Field or Lease Name New Mexico "P" State</p>		<p>9. Well No. 5</p>
<p>10. Field and Pool, or Wildcat Wildcat</p>		<p>11. Elevation (Show whether DF, RT, GR, etc.) 3890' DF, 3880' Gr.</p>
<p>12. County Lea</p>		<p>13. Unit Letter E, 2,080 FEET FROM THE north LINE AND 660 FEET FROM THE west LINE, SECTION 9 TOWNSHIP 17-S RANGE 36-E N.M.P.M.</p>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Started plugging operations 4-15-68. Set cement plugs as follows: #1, 8572-8490 w/25 sx Neat; #2, 7858-7770 w/25 sx Neat; #3, 6170-6080 w/25 sx Neat; #4, 5250-5160 w/25 sx Neat; #5, 2800-2740 w/25 sx Neat; #6, 1950-1910 w/25 sx Neat; #7 425-385 w/25 sx Neat; and #8, 30-0 w/ 10 sx Neat.

Left in hole: 11 3/4" casing, 42#, set at 369 and 8 5/8" casing, 32 & 24# from 2750-5199. Cut 8 5/8" casing at 2750' and pulled.

Hole filled with 9.0# drilling mud between plugs.

Installed dry hole marker. Well P & A 11 AM 4-16-68.

New Mexico Oil Conservation Commission was notified by phone prior to plugging.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. J. Berry TITLE Unit Head DATE 5-7-68

APPROVED BY John W. Runyan TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: