State of New Mexico Energy, Minerals and Natural Resources Department

	Form	C-103
Revised	March 25	5, 1999

DISTRICT I				-	· ·		Revised March 25, 1999
					WELL API NO.		
			P.O. Box		30-025-22630		
DISTRICT III 1000 Rio Brazo	s Rd., Aztec, NI	M 87410	Santa	re, New Mex	ico 87504-2088	5. Indicate Type of Lease	rate 🛛 FEE 🗌
DISTRICT IV 2040 South Pac	heco, Sante Fe,	NM 87505				6. State Oil & Gas Lease	
						B-1520	110.
(DO NO	SUN USE THIS FO	IDRY NO RM FOR PR	TICES AND	REPORTS O	N WELLS EEPEN OR PLUG BACK TO A	V/////////	
	DIFFE	RENT RESE	RVOIR. USE "A	APPLICATION 1	FOR PERMIT"	7. Lease Name or Unit A	greement Name
-		(FORM	C-101) FOR SU	ICH PROPOSAL	.S)	Bridges State	
l. Type of Wo	ell:		Gas 🗖				
Well 4			Gas Well	Other Inj	ector		
2. Name of O	•	il Dood	ucina TV	O NI MAT.		8. Well No.	
3 Address of	Operator P.O.		ucing TX.	α N.M. 1	1C.	127	
J. Addiess of		BOX 4358 louston	•	TX	9. Pool name or Wildca		
4. Well Locat		- Custon			77210-4358	Vacuum; Grayburg-S	an Andres
	it Letter M	, 600	Feet From	The south	Line and 560		
		·			Line and	Feet From The west	Line
Sec	tion 24		Township		Range 34E	NMPH	Lea County
			////\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\	levation (Show w	hether DR, RKB, RT, GR, etc.)		
	11.0	Check A _l	ppropriate I	Box to Indic	cate Nature of Notice, I	Report, or Other Dat	a
NOTICE OF INTENTION TO:			SUBS	SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK \square PLUG AND ABANDON		abandon \square					
TEMPORARY VARIABLES			COMMENCE DRILLI	_			
PIII I OP A	LTER CASIN	G 🗆					& ABANDONMENT \square
I OLL OK A	LIER CASIN	3	MULTIPLE COMPLETIO	· · · · · · · · · · · · · · · · · · ·	CASING TEST AND (CEMENT JOB L	
OTHER:					THER: Mechanical Integrity Test		
12. Describe prowork) SEF	posed or compl	eted operatio	ons. (Clearly state	all pertinent det	ails, and give pertinent dates, inclugram of proposed completion or re	ding estimated date of starting	any proposed
7/31/02 Ran	mechanical i	integrity t	est Witnesse	ach welloofe dia	Brep Johnny Robinson.	completion)	71
		integracy t	cott Whitese	d by Miloc	D tep Journy Robinson.		
Test pressure	e (psig): 540	ı					
	,						
		Productio					
Initial	Tubing 540	Casing 0	Casing 0	9		1.	
15 Min.	540	Ŏ	0				
30 Min.	540	0	0				
MIT chart at	tached. Well	l tempora	rily abandon	ed. CIBP at	4400'.		11.
							C_{ij}
I hereby certify that the	information above is	true and complet	e to the best of my kno	wiledge and halist			
SIGNATURE L	Hann &	to his.		_	Staff Office Assistant		
SIGNATURE_	7 3	rece ji m	<u></u>	TIT	LE Staff Office Assistant	DA	TE 08/14/2002
TYPE OR PRINT NAM	Tiffany A	1. Stebbin	IS			TELEPHONE NO. (7	13) 431-1207
(This space for State Us	e)						
APPROVED BY				-		Ā	10.0
CONDITIONS OF APPROVAL IF ANY:			RIGINAL SIGNED BY	<i>B</i> X	16 2 1 2002 —		
							7
				40.4	- MELL KERKLOLINIÁJÍVÁ	II/STAFE MANIAOFE	

