

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
B-1520

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT TO DRILL" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator	8. Farm or Lease Name
Mobil Oil Corporation	Bridges State
3. Address of Operator	9. Well No.
Box 633, Midland, Texas 79701	115
4. Location of Well	10. Field and Pool, or Wildcat
UNIT LETTER <u>A</u> <u>900</u> FEET FROM THE <u>North</u> LINE AND <u>990</u> FEET FROM	Vac. Glorieta
THE <u>East</u> LINE, SECTION <u>25</u> TOWNSHIP <u>17-S</u> RANGE <u>34-E</u> N.M.P.M.	
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
4018 GR	Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Run tubing & spot 100' cement plug across Glorieta perms (6056-62') (25 x)
2. Circulate hole to mud laden fluid, 25x gel per 100 Bbls.
3. Spot 100' cement plug across top of salt section in 5-1/2" csg 1600-1700' 25x of cement.
4. Determine free point in 5-1/2" csg. - approx. 400'. Cut off & pull.
5. Spot 100' cement plug across cut off point.
6. Spot 10x of cement plug at surface.
7. Erect monument & clear location.

Notify NMOCC 24 hrs. before starting P&A 393-6161 verbally approved by John Runyan, Hobbs NMOCC on 12-19-74

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Christine O. Tucker TITLE Authorized Agent DATE 1-7-75

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: