

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E - 388	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- Dry Hole		7. Unit Agreement Name
2. Name of Operator Union Oil Company of California		8. Farm or Lease Name Midway State
3. Address of Operator P. O. Box 671 Midland, Texas 79701		9. Well No. 4
4. Location of Well UNIT LETTER C 730 FEET FROM THE North LINE AND 1980 FEET FROM THE West LINE, SECTION 12 TOWNSHIP 17-S RANGE 36-E NMPM.		10. Field and Pool, or Wildcat Lovington Devotion
15. Elevation (Show whether DF, RT, GR, etc.) 3836 DF		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Run open end tubing to 4436' and displace well fluid with 9.3# mud.
2. Pull tubing and shoot off 8-5/8" casing.
3. Pull and lay down 8-5/8" casing.
4. Displace fluid in hole with drilling mud.
5. Spot 25 sacks cement in and out of 8-5/8" casing stub.
6. Spot 25 sacks cement at the top of the salt.
7. Spot 25 sacks cement in and out of 11-3/4" surface pipe at 451'.
8. Remove all surface and well head equipment.
9. Spot 10 sacks cement at surface and install marker.
- 10.. Clean location and fill cellar.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED John R. Gray John R. Gray TITLE District Drilling Supt. DATE 7-28-70

APPROVED BY [Signature] TITLE NEW MEXICO DATE JUL 30 1970

CONDITIONS OF APPROVAL, IF ANY: