

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATION		

NEW MEXICO OIL CONSERVATION COMMISSION

Form O-100
Supersedes Old
O-102 and O-103
Effective 1-1-65

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR REPORTS TO BE MADE TO OTHERS OR PLUG BACK TO A DIFFERENT RESERVOIR. USE APPROPRIATE FORM FOR SUCH PURPOSES.)

1. CIL WELL ☒ GAS WELL ☐ OTHER ☐ <i>Drill.</i>	7. Unit Agreement Number
2. Name of Operator <i>Humble Oil & Refg Co.</i>	8. Form or Lease Name <i>New Mexico State</i>
3. Address of Operator <i>P.O. Box 1600 - Midland, Texas 79701</i>	9. Well No. <i>5</i>
4. Location of Well UNIT LETTER <i>F</i> <i>2080</i> FEET FROM THE <i>N</i> LINE AND <i>1800</i> FEET FROM THE <i>W</i> LINE, SECTION <i>17</i> TOWNSHIP <i>17S</i> RANGE <i>36E</i> NMPM.	10. Field and Pool, or Tract <i>Undesignated</i>
11. Deviation (Show whether DE, RT, GR, etc.)	12. County <i>Lea</i>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPERATIONS ☒
CASING TEST AND CEMENT JOBS ☒
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☒
OTHER ☐

17. Describe in report or Completed Operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

NR120. Spud well in @ 8:00 AM 6-5-70. Drilled to 400' and ran & set 400' - 11 3/4" OD 42# CSQ. And Cmt w/ 325 sax Cmt. Cmt circulated WOC 18 hrs. Test CSQ w/ 800 psi for 30 min and held OK. Drilled to 3400' and ran 3400' - 8 7/8" OD - 24 1/2 32# CSQ. Cmt w/ 550 sax. WOC 18 hrs. Test CSQ w/ 1000 psi for 30 min and held OK. Top Cmt 16 2200'. Drilled to 8254' and ran DST #1 in Abo. 8170-8254'. Tool open 1 1/2 hrs rec 330' - 620' cut mud, water avg 71,500 cph. Drilled to 8700' TD on 6-24-70. Log well from 8700' to surface. Requested and received telephone approval from N.Mex. Occ. Mr. Ramsey, to plug and abandon on 6-24-70. Set plug No 1 - 8150-8500' w/ 50 sax. Plug No 2 - 6300-6120' w/ 60 sax. Plug No 3 - 4800-4700 w/ 30 sax. Plug No 4 - 3450-3350 w/ 30' sax. No 5 - 20' to surface w/ 10 sax. Between plugs w/ mud laden fluid. Cleaned location and installed dry hole marker. P & A 6-25-70.

I, I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *A. L. Ramsey* TITLE *Unit Head*

DATE *7/8/70*

APPROVED BY *Nathan E. Clegg* TITLE *GIS INSPECTOR*

DATE *FEB 14 1972*

CONDITIONS OF APPROVAL, IF ANY: