			
NO. OF COPIES RECEIVED			Province A non-
DISTRIBUTION			Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CO	NSERVATION COMMISSION	C-102 and C-103
FILE		TOTAL COMMISSION	Effective 1-1-65
U.S.G.S.			5a. Indicate Type of Leage
LAND OFFICE			State X Fee
OPERATOR			5. State Oil & Gas Lease No.
			E-161-2
SUNDR	Y NOTICES AND REPORTS OF PLUS AND FOR PERMIT - " (FORM C-101) FOR S	N WELLS	
USE "APPLICATI	ION FOR PERMIT - " (FORM C-101) FOR S	BACK TO A DIFFERENT RESERVOR. UCH PROPOSALS.)	
OIL GAS			7. Unit Agreement Name
2. Name of Operator	OTHER.		
TEXACO Inc.			8. Farm or Lease Name
3. Address of Operator			New Mexico 'DJ' State
•	Now Movelon 00240		9. Well No.
P.O. Box 728 - Hobbs,	New Mex 1 CO 88240		1
n .	660 Name		10. Field and Pool, or Wildcat
UNIT LETTER,	660 FEET FROM THE Nort	1 LINE AND 660 FEE	T FROM Vacuum Abo North
THE West	18 17	25.5	
THE WEST LINE, SECTIO	N 18 TOWNSHIP 17-	RANGE JO-E	NMPM. (()))))))))))))))))))))))))))))))))))
	15. Elevation (Show wheth	er DF RT CR etc.)	
	4012' DF	,,,,	12, County
16. Check A		N. C.Y.	Lea
NOTICE OF IN	Appropriate Box To Indicate		
		SUBSEQ	UENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	7
TEMPORARILY ABANDON	Tara Managan	COMMENCE DRILLING OPNS.	ALTERING CASING
			PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	1 l }=	7
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB]
PULL OR ALTER CASING	CHANGE PLANS	1 l }=]
OTHER		OTHER Perforate &	Acidize
OTHER	erations (Clearly state all pertinent de	OTHER Perforate &]
OTHER	erations (Clearly state all pertinent de	OTHER Perforate &	Acidize
17. Describe Proposed or Completed Ope work) SEE RULE 1103. T.D. 8800', PBTD 8770'	erations (Clearly state all pertinent de	other Perforate & tails, and give pertinent dates, inc	Acidize X
other	prations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng W/2 JSPI 8642', 43'	casing test and cement JQB Perforate & Perforate & tails, and give pertinent dates, inc. at 8800'. 44', 50', 51', 52',	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize X luding estimated date of starting any proposed
other	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	rations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500	tails, and give pertinent dates, inc at 8800'. 44', 50', 51', 52', //packer set at 8550' gal stages w/2500 ga'	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
17. Describe Proposed or Completed Ope work) SEE RULE 1103. T.D. 8800', PBTD 8770' Perforated 5-1/2" casis 84', 91', 92', 93', 94 w/10,000 gals. 20% reta 8 ball sealers between	erations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500 en each stage. Swab we	casing test and cement JQB Perforate & Perforate & tails, and give pertinent dates, inc. at 8800'. 44', 50', 51', 52', packer set at 8550' gal stages w/2500 ga's 11.	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
17. Describe Proposed or Completed Ope work) SEE RULE 1103. T.D. 8800', PBTD 8770' Perforated 5-1/2" casis 84', 91', 92', 93', 94 w/10,000 gals. 20% reta 8 ball sealers between	erations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500 en each stage. Swab we	casing test and cement JQB Perforate & Perforate & tails, and give pertinent dates, inc. at 8800'. 44', 50', 51', 52', packer set at 8550' gal stages w/2500 ga's 11.	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
OTHER	erations (Clearly state all pertinent de , 5-1/2" 17# Casing set ng w/2 JSPI 8642', 43' '. Ran 2-3/8" tubing warded acid in 4 - 2500 en each stage. Swab we	casing test and cement JQB Perforate & Perforate & tails, and give pertinent dates, inc. at 8800'. 44', 50', 51', 52', packer set at 8550' gal stages w/2500 ga's 11.	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
17. Describe Proposed or Completed Ope work) SEE RULE 1103. T.D. 8800', PBTD 8770' Perforated 5-1/2" casts 84', 91', 92', 93', 94 w/10,000 gals. 20% reta 8 ball sealers between	erations (Clearly state all pertinent de , 5-1/2" 17# Casing set ing w/2 JSPI 8642', 43' i. Ran 2-3/8" tubing warded acid in 4 - 2500 en each stage. Swab we	casing test and cement JQB Perforate & Perforate & Perforate & Perforate & tails, and give pertinent dates, inc. at 8800'. 44', 50', 51', 52', packer set at 8550' gal stages w/2500 ga's 11.	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations Is of treated gel water
17. Describe Proposed or Completed Ope work) SEE RULE 1103. T.D. 8800', PBTD 8770' Perforated 5-1/2" casis 84', 91', 92', 93', 94 w/10,000 gals. 20% retains 8 ball sealers between 8	erations (Clearly state all pertinent de , 5-1/2" 17# Casing set ing w/2 JSPI 8642', 43'. '. Ran 2-3/8" tubing warded acid in 4 - 2500 en each stage. Swab we	casing test and cement JQB Perforate & Per	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations
17. Describe Proposed or Completed Ope work) SEE RULE 1103. T.D. 8800', PBTD 8770' Perforated 5-1/2" casts 84', 91', 92', 93', 94 w/10,000 gals. 20% reta 8 ball sealers between 8 ba	erations (Clearly state all pertinent de , 5-1/2" 17# Casing set ing w/2 JSPI 8642', 43' i. Ran 2-3/8" tubing warded acid in 4 - 2500 en each stage. Swab we be each stage. Swab we Assertice Sup	casing test and cement JQB Perforate & Per	Acidize Nate December 1, 1971
17. Describe Proposed or Completed Ope work) SEE RULE 1103. T.D. 8800', PBTD 8770' Perforated 5-1/2" casis 84', 91', 92', 93', 94' w/10,000 gals. 20% retains 8 ball sealers between	erations (Clearly state all pertinent de , 5-1/2" 17# Casing set ing w/2 JSPI 8642', 43'. '. Ran 2-3/8" tubing warded acid in 4 - 2500 en each stage. Swab we	casing test and cement JQB Perforate & Per	Acidize Ruding estimated date of starting any proposed 53', 74', 81', 82', 83', Acidized perforations Is of treated gel water

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

DET - 8 1971

OIL CONSERVATION COMM.