NO. OF COPIES RECEIVED		
DISTRIBUTION		From C. 162
DISTRIBUTION		Form C-103 Supersedes Old
SANTA FE	NEW MEXICO OIL CONSERVATION COMMISSION	C+102 and C-103
FILE		Effective 1-1-65
U.S.G.S.		5a. Indicate Type of Lease
LAND OFFICE		State X Fee
OPERATOR		5. State Oil & Gas Lease No.
		E-161-2
SUNE	DRY NOTICES AND REPORTS ON WELLS	
USE **APPLIC	PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. CATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	
011 197 545		7. Unit Agreement Name
WELL X WELL 2. Name of Operator	OTHER-	
TEXACO Inc.		8. Farm or Lease Name
3. Address of Operator		New Mexico 'DJ' State
•	New Mouries 00040	9. Well No.
Location of Well	s, New Mexico 88240	1
	CCO	10. Field and Pool, or Wildcat
UNIT LETTER	660 FEET FROM THE North LINE AND 660	Vacuum Abo North
THE WEST LINE, SEC	TION 18 TOWNSHIP 17-S RANGE 35-E	MARIN ALLEMAN AND AND AND AND AND AND AND AND AND A
mmmmm		
	15. Elevation (Show whether DF, RT, GR, etc.)	12. County
	4012 DF Appropriate Box To Indicate Nature of Notice, Report of	Lea ()
7. Describe Proposed or Completed (work) SEE RULE 1103.	Operations (Clearly state all pertinent details, and give pertinent dates, incl. Total Depth 8800'	uding estimated date of starting any propose
	0 7 105 00 048 11 77 - 4	
	8-5/8" UD 24# K-55 Casing set at 1	8001
an 8789' (276 Joints) 00 sx Class 'C' w/10#	8-5/8" OD 24# K-55 Casing set at 155-1/2" 14 & 17# casing and set at 8800'. Cemsalt/sx. Plug at 8770'. Job complete 6:30 P	ented with 2770 av TIU 1
ested 5-1/2" casing wi	5-1/2" 14 & 17# casing and set at 8800'. Cemsalt/sx. Plug at 8770'. Job complete 6:30 P	ented with 2770 sx TLW + .M. 11-20-71.
ested 5-1/2" casing wi	5-1/2" 14 & 17# casing and set at 8800'. Cemsalt/sx. Plug at 8770'. Job complete 6:30 P	ented with 2770 sx TLW + .M. 11-20-71.
ested 5-1/2" casing wi	5-1/2" 14 & 17# casing and set at 8800'. Cemsalt/sx. Plug at 8770'. Job complete 6:30 P	ented with 2770 sx TLW + .M. 11-20-71.
ested 5-1/2" casing wi	5-1/2" 14 & 17# casing and set at 8800'. Cemsalt/sx. Plug at 8770'. Job complete 6:30 P	ented with 2770 sx TLW + .M. 11-20-71.
OU SX CIASS C W/ IU#	5-1/2" 14 & 17# casing and set at 8800'. Cemsalt/sx. Plug at 8770'. Job complete 6:30 P	ented with 2770 sx TLW + .M. 11-20-71.
ested 5-1/2" casing wi .K. Job completed 8:3	5-1/2" 14 & 17# casing and set at 8800'. Cemsalt/sx. Plug at 8770'. Job complete 6:30 Plith 1500# for 30 minutes from 8:00 A.M 8:30 A.M. 11-24-71.	ented with 2770 sx TLW + .M. 11-20-71.
ested 5-1/2" casing wi .K. Job completed 8:3	5-1/2" 14 & 17# casing and set at 8800'. Cemsalt/sx. Plug at 8770'. Job complete 6:30 P	ented with 2770 sx TLW + .M. 11-20-71.

DEC 1 1971

Orig. Signed by
Joe D. Ramey
CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

8675 1971

HOBBS N. M.