## State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103

OIL CONCEDUATION DIVISION

Revised 1-1-89

| P.O. Box 1980, Hobbs, NM 88240  | P.O. Box 208  |                                     | WELL API NO.                                 |  |
|---|---|-------------------------------------|--|--|
| DISTRICT II P.O. Drawer DD, Artesia, NM 88210   | Santa Fe, New Mexico  | =                                   | 30-025-23903                                 |  |
| DISTRICT III  |   |                                     | 5. Indicate Type of Lease STATE X FEE        |  |
| 1000 Rio Brazos Rd., Aztec, NM 87410  |   |                                     | 6. State Oil & Gas Lesse No.<br>A-1320       |  |
| ( DO NOT USE THIS FORM FOR PRO<br>DIFFERENT RESER<br>(FORM C                                      | ICES AND REPORTS ON WEL<br>OPOSALS TO DRILL OR TO DEEPEN<br>RVOIR. USE "APPLICATION FOR PEI<br>-101) FOR SUCH PROPOSALS.) | OR PLUG BACK TO A                   | 7. Lease Name or Unit Agreement Name         |  |
| 1. Type of Well: OL GAS WELL GAS  | ones Water  | Injection                           | East Vacuum Gb/SA Unit                       |  |
| 2 Name of Operator Phillips Petroleum   | Company   |                                     | 8. Well No. Tract 3202                       |  |
| 3. Address of Operator 4001 Penbrook Stree  | et, Odessa, TX 79762  |                                     | 9. Pool name or Wildcat Vacuum Gb/SA         |  |
| 4. Well Location  |   |                                     | research co/pri                              |  |
| Unit Letter B : 990   | Feet From The North   | Line and                            | Feet From The East Line                      |  |
| Section 32  | Township 17-S Ra  | nge 35-E                            | NMPM Lea County                              |  |
|   | 10. Elevation (Show whether 3965 'GL;   | DF, RKB, RT, GR, etc.)<br>3975' RKB | <i>*////////////////////////////////////</i> |  |
| 11. Check   | Appropriate Box to Indicate 1   |                                     | eport, or Other Data                         |  |
| NOTICE OF IN  | TENTION TO:   | SUB                                 | SEQUENT REPORT OF:                           |  |
| PERFORM REMEDIAL WORK   | PLUG AND ABANDON  | REMEDIAL WORK                       | ALTERING CASING                              |  |
| TEMPORARILY ABANDON   | CHANGE PLANS  | COMMENCE DRILLING                   | OPNS. PLUG AND ABANDONMENT                   |  |
| PULL OR ALTER CASING  |   | CASING TEST AND CE                  | BOL TNAM:                                    |  |
| OTHER:  | ·   | OTHER: Converte                     | ed to water injection X                      |  |
| 12. Describe Proposed or Completed Open<br>work) SEE RULE 1103.                                   | sticos (Clearly state all pertinent details, as   | nd give pertinent dates, include    | ting estimated date of starting any proposed |  |
| 12-13-93 - RU DDU CO  | OOH LD Rods and pump.   |                                     |  |  |
| 12-14-93 - COOH w/tbg. PU GIH bit, collars, and tubing. Drill on fill and CIBP.                   |   |                                     |  |  |
| Circulate clean. 12-15-93 - Clean out to 4697'. GIH w/casing scraper.                             |   |                                     |  |  |
| 12-16-93 - COOH w/tbg. and scraper. GIH w/RBP and tbg. Set RBP @3000'. Load and                   |   |                                     |  |  |
| test to 1000#. O.K. 12-17-93 - Perf. w/4" csg. gun @2 SPF as follows: 4639'-4674', 35', 70 shots; |   |                                     |  |  |
| 4622′-4626  | 5', 4', 8 shots; 4601   | .'-4615', 14',                      | 28 shots; 4502'-4520', 18',                  |  |
|   | 4420'-4444', 24', 48<br>i tbg. Set pkr @4305  |                                     | -4408',12', 24 shots. GIH                    |  |
| 12-20-93 - Pump 20 Bb   |   | 430. Mix 3 di                       | rums TC-405 in 165 gals. FW.                 |  |
| 12-21-93 - Release pl   | cr. Move up hole and  | reset @3927' a                      | and tailpipe @4301'.                         |  |
| 12-22-93 - MI RU Test   | t lines. Pmp 4500 ga  | als. Fercheck :                     | SC acid. (Over)                              |  |
| I hereby certify that the information above is tre  | · ~ · · ·   |                                     | 355-1  |  |
|   | •   | supv.kegula                         | tory Affairs DATE 01-21-94                   |  |
| TYPE OR PRINT NAME L. M. Sax  | nders   |                                     | (915)<br>TELEPHONE NO. 368-1488              |  |
| (This space for State Use)  ORIGINAL SIGNED BY JERRY SEXTON  JAN 9 # 190/                         |   |                                     |  |  |
|   | TRICT I SUPERVISOR  | n e                                 | JAN 26 1994                                  |  |
| CONDITIONS OF APPROVAL, IF ANY:   | π   | re                                  | DATE   |  |

East Vacuum Gb/SA Unit-Tract 3202 Well No. 033 Vacuum Gb/SA API No. 30-025-23903 Lease No. A-1320 Lea County, NM Form C-103

| 12-23-93 | Swab.   |
|----------|---|
| 12-28-93 | COOH LD Tbg. and pkr. PU GIH w/inj pkr and Duo-line inj. tbg.               |
| 12-29-93 | Set pkr. Flange up wellhead. Test backside to 500# w/chart. 0.K. RD DDU MO. |
| 12-30-93 | Temporarily suspend until injection starts.                                 |

01-21-94 AF:ehg

RegPro: AFran: EVGBU033.103