STATE OF HERV MEXICO ENERGY AND MINERALS DEPARTMENT

MB. BF,COPIES RECEIVED		
DISTRIBUTION	1	
SANTA FE		
FILE	Ţ	
U.S.G.S,		
LAND OFFICE		
OPPRALOR	1	

OIL CONSERVATION DIVISION P. O. BOX 2088 SANTA FE, NEW MEXICO 87501

Form C-103 Revised 10-1-78

Fee

5a. Indicate Type of Lease

State X

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL ON TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
	B-1030-1	mmi
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)		
OIL GAS WELL OTHER-	7. Unit Agreement	
Name of Operator TEXACO INC.	8. Farm or Lease	Name
Address of Operator	North Vacuu	m Abo West
P.O. Box 728, Hobbs, NM 88240	16	
F 1980 North 1980 UNIT LETTER FEET FROM THE LINE AND FEET FR	North Vacuum	n Abo
West 28 17-S 34-E		
15. Elevation (Show whether DF, RT, GR, etc.)	12. County	
4065' (GR)	Lea	
Check Appropriate Box To Indicate Nature of Notice, Report or (Other Data NT REPORT OF:	
PLUG AND ABANDON REMEDIAL WORK	ALTERIA	VG CASING
EMPORARILY ABANDON COMMENCE DRILLING OPNS.		D ABANDONMENT
CHANGE PLANS CASING TEST AND CEMENT JOB OTHER CONVERT TO IT	jection	ρX
OTHER		£
 Rigged up. Pld rds and pump. Installed BOP. Pld tub Set pkr @ 8736'. A/perfs 8777-8859' w/10,000 gals 30# 	····•	
rock salt between stages. Flush w/2500 gals gelled br 3. Ran 2-3/8" plastic coated tbg w/packer and set @ 8738' annulus w/inhibited water. 4. Complete as shut-in water injection, waiting on inject	500# ine. . Load	
rock salt between stages. Flush w/2500 gals gelled br Ran 2-3/8" plastic coated tbg w/packer and set @ 8738' annulus w/inhibited water.	500# ine. . Load	
rock salt between stages. Flush w/2500 gals gelled br 3. Ran 2-3/8" plastic coated tbg w/packer and set @ 8738' annulus w/inhibited water. 4. Complete as shut-in water injection, waiting on inject	500# ine. . Load	
rock salt between stages. Flush w/2500 gals gelled br 3. Ran 2-3/8" plastic coated tbg w/packer and set @ 8738' annulus w/inhibited water. 4. Complete as shut-in water injection, waiting on inject	500# ine. . Load	
rock salt between stages. Flush w/2500 gals gelled br 3. Ran 2-3/8" plastic coated tbg w/packer and set @ 8738' annulus w/inhibited water. 4. Complete as shut-in water injection, waiting on inject	500# ine. . Load	
rock salt between stages. Flush w/2500 gals gelled br 3. Ran 2-3/8" plastic coated tbg w/packer and set @ 8738' annulus w/inhibited water. 4. Complete as shut-in water injection, waiting on inject	500# ine. . Load	
rock salt between stages. Flush w/2500 gals gelled br 3. Ran 2-3/8" plastic coated tbg w/packer and set @ 8738' annulus w/inhibited water. 4. Complete as shut-in water injection, waiting on inject 10-11-84.	500# ine. . Load	
rock salt between stages. Flush w/2500 gals gelled br 3. Ran 2-3/8" plastic coated tbg w/packer and set @ 8738' annulus w/inhibited water. 4. Complete as shut-in water injection, waiting on inject	500# ine. . Load ion line,	ber 1, 1 9 84