

11/2/94 Increase pressure to 4400 psig
5/24/91 Inj. press. Incr to 3930 psig

R-5801 Inj. Well
NSL-547