

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240
DISTRICT II
P.O. Drawer DD, Artesia, NM 8210
DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-24126
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	B-1501
7. Lease Name or Unit Agreement Name	SANTA FE
8. Well No.	124
9. Pool name or Wildcat	VACUUM ABO, NORTH

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762	
4. Well Location Unit Letter <u>D</u> : <u>5200</u> Feet From The <u>NORTH</u> Line and <u>5200</u> Feet From The <u>WEST</u> Line Section <u>29</u> Township <u>17 S</u> Range <u>35 E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3976' GR	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/26/95 NOTIFIED NMOCD (B. HILL) OF INTENT TO P&A.

NUCLASS 1 MANUAL BOPE. PULLED PRODUCTION TBG. SDON.

4/27/95 GIH W/5.5" CIBP & WS TO 8190 & SET CIBP, MIS 80 SXS SALT GEL & CIRC W/65 BBLS

NOTE: PLUGS #'S 1-8 ARE ALL CLASS "C" CEMENT 14.8 PPG & 1.32 CFPS.

PUMP PLUG #1, 25 SXS, INTERVAL 8190'-7950', TOC @ 7950', PULLED UPHOLE TO 7481'.
PUMP PLUG #2, 25 SXS, INTERVAL 7481'-7241', TOC @ 7241', PULLED UPHOLE TO 6456'.
PUMP PLUG #3, 25 SXS, INTERVAL 6456'-6216', TOC @ 6216', PULLED UPHOLE TO 6056'.
PUMP PLUG #4, 25 SXS, INTERVAL 6056'-5816', TOC @ 5816', PULLED UPHOLE TO 4215'.
PUMP PLUG #5, 25 SXS, INTERVAL 4215'-3975', TOC @ 3975', PULLED UPHOLE TO 2928'.
PUMP PLUG #6, 25 SXS, INTERVAL 2928'-2888', TOC @ 2688', PULLED UPHOLE TO 1754'.
PUMP PLUG #7, 25 SXS, INTERVAL 1754'-1514', TOC @ 1514', PULLED UPHOLE TO 408'.

(OVER)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Regulation Specialist DATE 5/10/95

TYPE OR PRINT NAME L. M. SANDERS TELEPHONE NO. 915/368-1488

(This space for State Use)

APPROVED BY Johnny Robinson TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY _____

JC

4/27/95 PUMP PLUG #8, 25 SXS, INTERVAL 408'-3', CEMENT
CIRCULATED TO SURFACE LEAVING INSIDE OF 5.5"
CASING FULL.
RDMO SIERRA WELL SERVICE RIG #3.
WELL IS PLUGGED AND ABANDONED

RECEIVED

OFFICE