

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-86

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" FORM C-101 FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Texas American Oil Corporation	8. Farm or Lease Name Shaw
3. Address of Operator 300 West Wall - Suite 400 Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER B 660 FEET FROM THE N LINE AND 1980 FEET FROM THE E LINE, SECTION 15 TOWNSHIP 17S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Humble City Strawn
11. Elevation (Show whether DF, RT, GR; etc.) 3752' GL	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4/9/85 Pref & test Lower Strawn 11,432-11,450 Noncommercial.  
4/12/85 Set CIBP @ 11,250' w/20 sx cement. Perf & test interval from 10,950'-10,290'.  
4/25/85 - 7/1/85 Test pump.  
Well temporarily abandon 11/15/85.  
Propose to P/A well as follows: Marrs Casing Service, Kermit Texas.  
1. Set 100' Cement plug @ 9,000'.  
2. Set 100' cement plug @ 6,855'.  
3. Set 100' cement plug @ 4,322; & tap up.  
4. Set 100' cement plug @ 3,150'.  
5. Perf or pull 8 5/8" @ 2,100'; w/100' cement plug @ 2,100'.  
6. Set 100' cement plug @ 420'.  
7. Set 50' cement plug in 11 3/4" @ 370'.  
8. Set 10' cement plug @ surface.  
9. Install dry hole marker.

THIS DOCUMENT IS THE PROPERTY OF THE NEW MEXICO OIL CONSERVATION COMMISSION. IT IS TO BE RETURNED TO THE COMMISSION UPON REQUEST.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R.D. Henson (R.D. Henson) TITLE District Manager DATE 11-5-86

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT 1 SUPERVISOR TITLE  DATE NOV 7 1986

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
NOV 6 1986  
COPIES OFFICE  
HOBBS OFFICE

TEXAS AMERICAN OIL CORPORATION  
Shaw #1  
Humble City Field  
Lea County, New Mexico  
660' FNL & 1980' FEL Section 15, T17S, R37E

