

COPIES RECEIVED

NOTIFICATION

OFFICE

FOR

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease

State ☒Fee ☐

5. State Oil & Gas Lease No.

B-1334

SUNDRY NOTICES AND REPORTS ON WELLS

DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.WELL ☒GAS WELL ☐OTHER ☐

Name of Operator

Skelly Oil Company

Address of Operator

P. O. Box 1351, Midland, Texas 79701

4. Location of Well

UNIT LETTER **B** **660** FEET FROM THE **North** LINE AND **1980** FEET FROM
East **20** TOWNSHIP **17S** RANGE **35E** NMPM.

7. Unit Agreement Name

8. Farm or Lease Name

State "AC"

9. Well No.

1

10. Field and Pool, or Wildcat

Vacuum Grayburg-San Andres

15. Elevation (Show whether DF, RT, GR, etc.)

3985' RT

12. County

Lee

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐TEMPORARILY ABANDON ☐PULL OR ALTER CASING ☐OTHER ☐PLUG AND ABANDON ☒CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐COMMENCE DRILLING OPER. ☐CASING TEST AND REMOVAL JOB ☐OTHER ☐ALTERING CASING ☐PLUG AND ABANDONMENT ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated dates, including any proposed work) SEE RULE 1103.

- 1) Move in workover rig. Pull rods and tubing.
- 2) Set cast iron bridge plug at 4500' and spot 35' of cement on top.
- 3) Set cement plug 1800-1900'.
- 4) Set cement plug from 100' to surface.
- 5) Install dry hole marker.

Note: All intervals not cemented will be filled with 10% mud.

add 20' of cement on top of plug at 6420'-
 35' cement minimum on top of C.I.B.P.

18. I hereby certify that the information above is true and complete to the best of my knowledge.

(Signed) D. R. Crow

D. R. Crow

Lead Clerk

SIGNED

TITLE

Sept. 4, 1973

APPROVED BY

CONDITION OF APPROVAL, IF ANY:

TITLE

DATE