

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-24675
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name	EAST VACUUM GB/SA UNIT TRACT 2672
8. Well No.	008
9. Pool name or Wildcat	VACUUM GRAYBURG/SAN ANDRES
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	3914' GL

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER	2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook Street, Odessa, TX 79762	4. Well Location Unit Letter <u>B</u> : <u>990'</u> Feet From The <u>FNL</u> Line and <u>2310'</u> Feet From The <u>FEL</u> Line
5. Section <u>26</u> Township <u>T-17-S</u> Range <u>R-35-E</u> NMPM <u>LEA</u> County	6. 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3914' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: REPERF & STIMULATE ABANDONED PERFS ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

05/22/97 MIRU DA&S #291, COOH W/RODS & PMP, NU BOP & PAN, COOH W/TBG, GIH W/KS.
05/23/97 COOH W/KS, MIRU DAVIS TL REV UNIT, PU GIH W/6-1/4" BIT, COLLARS & TBG, TAG FILL @ 4548', BRK CIRC & DRL 2", START OUT HOLE W/BIT, SISD.
05/24/97 COOH W/BIT, GIH W/MILL, TAG JK @ 4548' MILL T/+-4550', CIRC CLN, PULL ABOVE PERFS.
05/25/97 GIH MILL F/+-4550-4552', CIRC CLN, START OUT HOLE.
05/26/97 COOH W/MILL, GIH W/BIT, DRL OUT RET & CMT T/4680', CIRC CLN, START OUT HOLE.
05/27/97 COOH LD COLLARS & BIT, MIRU HLS, LOG & PERF W/4" CSG GUNS @ 4 SPF W/PREM CHRGS: 4583-4588', 5', 20 SHOTS; 4573-4577', 4', 16 SHOTS; 4567-4570', 3', 12 SHOTS; 4563-4565', 2', 8 SHOTS, RDMO HLS, GIH W/SCRPR T/4623', START OUT HOLE.
05/28/97 COOH W/SCRPR & KS, MIRU TBG TSTRS, TST IN HOLE W/RBP & PKR, SET RBP @ 4598' & PKR @ 4550', RDMO TSTRS, MIRU HES T/ACIDIZE, TST LNS, ATTEMPT T/ACIDIZE PERFS @
(CONTINUED ON BACK)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Larry M. Sanders

TITLE Senior Regulation Analyst DATE 06/23/97

TYPE OR PRINT NAME

Larry M. Sanders

TELEPHONE NO. (915) 368-1488

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

mf

05/28/97 CONTINUED

4563-4588', COMMUNICATED W/PERFS @ 4484-4536', FLUSH TBG, REL PKR & PULL ABOVE ALL PERFS, SD WAIT 1 HR WHILE HES RD, RE-SET PKR @ 4550' RU SWAB W/FL @ 300' REC 20 BBL, END FL @ 1500', SISD.

05/29/97 OPEN UP W/TBG ON VAC & FL @ 600', REC 100 BBL W/END FL @ 2400', SISD.

06/02/97 BLD DWN, REL PKR & RBP, COOH, GIH W/TP, PKR & SPOT CONTROL VLV, SET PKR @ 4408' W/TP @ 4599', MIRU PMP TRK, MIX & PMP 300 GAL XYKENE & 300 GALS TS-164, DISPL W/27 BBL FR WTR, SISD.

06/03/97 OPEN UP W/TBG ON 0#, FISH SPOT CONTROL VLV, SWAB BK 72 BBL, LD & TST BK SIDE T/500# OK, REL PKR, PULL UP & RESET @ 4223' W/TP @ 4413', LD BK SIDE, MIRU HES, TST LNS, PMP 2250 GAL 15% FERCK ACID, 2500# RK SALT IN 2500 BBL XLINK GELL BRINE W/BRKR & 38 BBL FR WTR FLUSH: 34 BBL FR WTR PAD, 1000# SALT IN 600 GALS XLINK, 750 GALS ACID; 500# SALT IN 500 GALS XLINK, 750 GALS ACID; 1000# SALT IN 720 GALS XLINK, 750 GALS ACID; FLUSH W/38 BBL FR WTR, ISIP 594# T MIN 214# 10 MIN 125# 15 MIN 81# MAX PRESS 1257# AVG RAGE 5 BPM, SI, RDMO HES, OPEN UP W/TBG ON VAC & FL @ SURF, REC 55 BBL W/END FL @ 1000', SISD.

06/04/97 OPEN UP W/50# ON TBG & FL @ 1000', REC 197 BBL W/END FL @ 1000', SISD.

06/05/97 REL PKR, COOH, GIH W/PROD TBG & TBG PMP BBL, ND PAN & BOP, FLNG UP WH, GIH W/5/8" & 3/4" RODS, COOH LD, GIH W/PLNGR & 7/8" RODS, SISD.

06/06/97 PU GIH W/7/8" & 1" RODS, SPACE OUT, STK OUT RODS, RDMO DDU, TEMP DROP F/REPORT, MOVING IN PMPNG UNIT.

06/20/97 PMP 24 HRS, TST 35 BOPD 812 BWPD 369.1 MCF 81% CO2.

06/21/97 PMP 24 HRS, TST 56 BOPD 741 BWPD 10.2 MCF 80% CO2.

06/22/97 PMP 24 HRS, TST 47 BOPD 736 BWPD 20.4 MCF 78% CO2.

COMPLETE DROP F/REPORT.