

COPIES RECEIVED		
DISTRIBUTION		
FE		
DATE		
RECEIVED		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Free <input type="checkbox"/>
5. State Oil & Gas Lease No.
L-6673

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Penroc Oil Corporation	8. Farm or Lease Name Humble-City State
3. Address of Operator P. O. Drawer 831, Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER C, 2086 FEET FROM THE West LINE AND 766 FEET FROM THE North LINE, SECTION 15 TOWNSHIP 17S RANGE 37E NMPM.	10. Field and Pool, or Wildcat Under Humble City Strawn
15. Elevation (Show whether DF, RT, GR, etc.) 3761' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK	<input type="checkbox"/>
TEMPORARILY ABANDON	<input type="checkbox"/>
PULL OR ALTER CASING	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

PLUG AND ABANDON	<input type="checkbox"/>
CHANGE PLANS	<input type="checkbox"/>
OTHER	<input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK	<input type="checkbox"/>	ALTERING CASING	<input type="checkbox"/>
COMMENCE DRILLING OPNS.	<input type="checkbox"/>	PLUG AND ABANDONMENT	<input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB	<input type="checkbox"/>	OTHER	<input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.

11/20/74 Drilled 7 7/8" hole to 11,660' Total Depth.

11/21/74 Set Plugs as follows:

35 sx	4650-4750'
35 sx	5080-5180'
35 sx	8883-8983'
35 sx	9772-9872'
35 sx	10260-10360'
35 sx	11454-11554'

12/13/74 Pulled 690' 8 5/8" casing

Set plugs as follows:

65 sx	640-740'
80 sx	329-429'

12/14/74 Set 10 sx plug in top of surface/& set Dry Hole Marker.

Commission will be notified when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>[Signature]</u>	TITLE <u>Prod. Superintendent</u>	DATE <u>1/10/75</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>[Signature]</u>	DATE <u>14Y 10 1975</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

JAN 15 1973

OIL CONSERVATION COMM.
HOEDS, H. M.