

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Geology, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Arizon Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-25068
1. Indicate Type of Lease	STATE ☐ FEED ☒
6. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		7. Lease Name or Unit Agreement Name Fannye M. Holloway
1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Chevron U.S.A. Inc.	8. Well No. 3
3. Address of Operator P.O. Box 670, Hobbs, NM 88240	9. Pool name or Wildcat Knowles South-Devonian	
4. Well Location Unit Letter <u>G</u> : 1980 Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>13</u> Township <u>17S</u> Range <u>38E</u> NMPM Lea County	10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3687'	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

IT IS PROPOSED TO PLUG AND ABANDON THE SUBJECT WELL

SET CIBP @ 9625'± CAP W/35' TEST CSG TO 500 PSI
200' BALANCED CMT PLUG F 9360 TO 9160 W/25 SX

6950 TO 6750 "
5480 TO 5280 "
5050 TO 4850 "
3600 TO 3400 "
2400 TO 2200 "

PERF 5 1/2" CSG @ 1050' SET CIRC @ 950' SQZ 9 5/8" x 5 1/2" W/140 SX CIRC CMT TO SURFACE
CAP CIRC @ 950' W/35' CMT

SET CMT PLUG F 370 TO 270' W/25 SX

SET 60" SURFACE PLUG W/15 SX

CUT OFF WH INSTALL DRYHOLE MARKER, CHANGE WELLBORE STATUS TO PLUGGED AND ABANDONED.

I hereby certify that the information above is true and correct to the best of my knowledge and belief.

SIGNATURE M. E. Akins 7/2/90 TITLE Staff Dir. Engr. DATE 7-2-90

TYPE OR NAME M. E. Akins

TELEPHONE NO. 393-4121

(This space for State Use) ORIGINAL SIGNED BY DISTRICT I SUPERVISOR

APPROVED BY _____
COORDINATOR OF APPROVAL & ACTION

THE COMMISSION MUST BE NOTIFIED OF ANY CHANGES TO THE INFORMATION CONTAINED HEREIN.
JUL 05 1990