F OF OPIES RECEIVED	t		Form C-103
DISTRIBUTION			Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OU CON	NEW MEXICO OIL CONSERVATION COMMISSION	
FILE	THE WILLIES OF CONS	SERVATION COMMISSION	Effective 1-1-65
	+		5a. Indicate Type of Lease
U.S.G.S.	+		State X Fee
OPERATOR OPERATOR	- - 		5. State Oil & Gas Lease No.
OPERATOR			B-871-1
	THURSE AND DEBORTS OF	we	vinninininin
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)			7. Unit Agreement Name
OIL GAS WELL	OTHER-		West Vacuum Unit
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name West Vacuum Unit		
3. Address of Operator			9. Well No.
P. O. Box 728, Hobbs, New Mexico 88240			10. Field and Pool, or Wildcat
UNIT LETTER K , 1466 FEET FROM THE South LINE AND 1375 FEET FROM			Understana ted
THE WEST LINE, SECTION 34 TOWNSHIP 17-S RANGE 34-E NMPM.			
······································	TITTLE CLASSIC COLORS	DE PT CP	
	15. Elevation (Show whether		12. County
	4033' (Lea (\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:			
	[ļ	
PERFORM REMEDIAL WORK	PLUG AND ABANDON	REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON		COMMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	CHANGE PLANS	other Perforate &	Mmont
		OTHER PERIORATE &	Treat
OTHER]	
2. Set packer 3. Acidize $5\frac{1}{2}$ Ball Sealer 4. Frac $5\frac{1}{2}$ OD Polymer in 2 stages us 5. Swab Well. 6. Install Ele	<pre>@ 4381'. OD Casing perforations</pre>	Depth 4770' set @ 370' et @ 4800' 4493', 4545', 57',4 4493'-4672' w/2000 -4672' w/20,000 gal /40 sand & 4000 gal. lakes & 200# Rock Sa	gal. 15% NE Acid w/30 . Cross-Link 10/20 sand in lt between stages.
18. I hereby certify that the info	July Setted	of my knowledge and belief. Asst. Dist. Supt.	DATE 1-20-76
\mathcal{U}	Park & Survey		المنافعة
APPROVED BY			DATE

~*