

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/> Re-entry & Plugging	7. Unit Agreement Name
2. Name of Operator TXO Production Corp.	8. Farm or Lease Name Hightower
3. Address of Operator 900 Wilco Bldg., Midland, TX 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>A</u> <u>810</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>East</u> LINE, SECTION <u>4</u> TOWNSHIP <u>17-S</u> RANGE <u>37-E</u> NMPM.	10. Field and Pool, or Wildcat Shipp Strawn
15. Elevation (Show whether DF, RT, GR, etc.) 3778' GL & 3794 KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☒ and
CASING TEST AND CEMENT JOB ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1-30-88 RU unit f/re-entry.
1-31-88 Drld cmt to 745'.
2-1-88 Drld cmt to 1123'.
2-2-88 Drld cmt to 1269'.
2-3-88 TOH. Ran CCL. Set dn @ 1254'. GIH w/fish finder tool. Top of fish @ 1118'. GIH w/bit. Ream & wash. Md 155' of hole. Torqueing badly. TOH. TIH w/bit. Tag fill @ 1119'. Bit rolling off fish. POH. GIH. Ream & wash f/939'. Drld on fish 4½ hrs. Rec 75% cmt, 25% redbeds, lots of metal at first, at end only redbed.
2-4-88 Drlg on fish 1 hr. Bit on outside of csg. TOH. TIH w/new bit. Tag fish @ 1123'. Work bit 2 hrs. Bit outside of csg. TIH w/10½" OD shoe & 1 jt wash pipe. Wash to 1089'. Torque f/750 to 900#.
2-5-88 Drld w/shoe f/1089-1144'. Rec 50% cmt, 50% redbed. Work over fish. Rec show of metal. Torque 750-1500#. At end of day, 5% cmt, 95% redbed.
2-6-88 Drld w/washover shoe f/1144-1152'. Tagged top of 8 5/8" csg and stalled out swivel. Work back to top of fish. Torque 1350-1600#. Circ. Rec small amount iron. RU csg crew. RIH w/csg patch bowl & csg. Tag top of 8 5/8" csg w/1000# weight. Bowl slipped off csg. Work trying to catch csg w/lip on csg patch. Could not catch. TIH inside 8 5/8" w/bull plug, subs & DP. Tagged top of 8 5/8" csg. Bull plug rolled off. TOH w/bull plug. Tag top of 8 5/8" csg w/bit. (cont.)

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>Beth Cune</u>	TITLE <u>Secretary</u>	DATE <u>2-16-88</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>OIL & GAS INSPECTOR</u>	DATE <u>APR 5 1988</u>
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

FEB 17 1988

OCD

HOBBY OFFICE

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State ☐ Fee ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Re-entry & Plugging	7. Unit Agreement Name
2. Name of Operator TXO Production Corp.	8. Farm or Lease Name Hightower
3. Address of Operator 900 Wilco Bldg., Midland, TX 79701	9. Well No. 1
4. Location of Well UNIT LETTER A 810 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 4 TOWNSHIP 17-S RANGE 37-E NMPM.	10. Field and Pool, or Wildcat Shipp Strawn
15. Elevation (Show whether DF, RT, GR, etc.) 3778' GL & 3794' KB	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☒ and
CASING TEST AND CEMENT JOBS ☐
OTHER ☐
ALTERING CASING ☐
PLUG AND ABANDONMENT ☒

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

cont.
2-6-88 Bit still rolling off. TOH. TIH w/drag bit, subs & DP. Tag top of 8 5/8" csg. Still fell dn beside csg.
2-7-88 TOH w/drag bit. TIH w/lip guide shoe, subs & DP. Tag top of fish @ 1123'. Turn 1/4 turn & fell off. PU & turn 1/4 turn & set dn on fish. Turn 1/2 turn & fell off. TOH w/drag bit & csg bowl. TIH w/impression block. TOH. TIH w/drag bit, DCs & DP. Circ bottom up twice. Rec small amount of redbed. TOH w/bit. TIH w/long wall hook w/csg patch. Attempt to hook 8 5/8" csg f/1 1/2 hrs, could not. Loss 3' hole last attempt. TOH w/csg wall hook, turned inside. No way for 8 5/8" csg to get inside.
2-8-88 LD 8 5/8" csg wall hook. Bottom of hook rolled in & turned up. TIH w/DP. Set 100 sx "H" plug @ 1129'. Set 100 sx "C" plug w/2% CaCl @ 421'. Set 10 sx "C" plug w/2% CaCl @ surf. Weld on plate and dry hole marker. WELL PLUGGED AND ABANDONED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Beth Cune TITLE Secretary

DATE 2-16-88

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

OIL & GAS INSPECTOR

DATE 2-16-88