

Farmland International Energy Co.
Hooper No. 1

Drillstem Tests Results

DST No. 1	8170-8310			
	T/O 22" on 1st flow and 120" on 2nd flow			
	Recovered 40' drilling fluid.			
	IHH	3811	FHH	3788
	IF	46	FF	23
	45" ISI	23	60" FSI	43
DST No. 2	9320-9435			
	T/O 20" on 1st flow and 1'40" on 2nd flow			
	Recovered 150' drilling fluid.			
	IHH	4369	FHH	4369
	IF	117	FF	141
	45" ISI	188	120" FSI	188
DST No. 3	10,685-10,745			
	T/O 20" on 1st flow and 180" on 2nd flow			
	Recovered 1500' water blanket and 1000' condensate			
	IHH	5311	FHH	5192
	IF	647	FF	818
	90" ISI	910	6-1/2" FSI	924
DST No. 4	12,326-12,719			
	T/O 15" on 1st flow and 6' on 2nd flow			
	Recovered 1800' GIDP, 3000' GCWB and 663' GCDF			
	IHH	7242	FHH	7103
	IF	1533	FF	1894
	60" ISI	6014	5' FSI	6405