

Submit 3 Copies To Appropriate District  
Office

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 South First, Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION  
2040 South Pacheco  
Santa Fe, NM 87505

Form C-103  
Revised March 25, 1999

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-25704
1. Type of Well: Oil Well <input type="checkbox"/> Gas Well <input type="checkbox"/> Other Injector <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
2. Name of Operator Texaco Exploration & Production, Inc.		6. State Oil & Gas Lease No. B-1565
3. Address of Operator P. O. Box 3109, Midland, TX 79702		7. Lease Name or Unit Agreement Name: Central Vacuum Unit
4. Well Location Unit Letter <u>C</u> : <u>60</u> feet from the <u>North</u> line and <u>2552</u> feet from the <u>West</u> line Section <u>36</u> Township <u>17S</u> Range <u>34E</u> NMPM Lea County		8. Well No. 41
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Vacuum Grayburg/SA

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
<b>NOTICE OF INTENTION TO:</b> PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input checked="" type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	<b>SUBSEQUENT REPORT OF:</b> REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

1. RIH w/Tbg Tag CIBP @ 4280' (San-Andres) Spot 25 Sx plug 4280'-4100'
2. Displace hole w/MLF, 9.5# Brine w/25# Gel P/BBL
3. Spot 25 Sx plug 3500'-3200' (Queen)
4. Spot 25 Sx plug 2900'-2600' (B-Salt, Yates)
5. Spot 25 Sx plug 1300'-1000' (T-Salt, Bad csg @ 1170') WOC Tag
6. Spot 25 Sx plug 500'-200' (8 5/8" shoe) - T-1
7. 10 Sx plug 10'-Surf, Install dry holy marker

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. T. Corbett TITLE FACILITY ENGR DATE 1/22/01  
Type or print name JAMES T. CORBITT Telephone No. 915 688-4432  
(This space for State use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE 1/22/01  
Conditions of approval, if any: