

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT  
N.M. Oil Cons. Division

FORM APPROVED  
Budget Bureau No. 1004-0135  
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

P.O. Box 1980  
Albuquerque, NM 88241

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.  
Use "APPLICATION FOR PERMIT-" for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☐ Oil Well ☒ Gas Well ☐ Other

2. Name of Operator

Matador Operating Company

3. Address and Telephone No.

415 W. Wall, Ste. 1101 Midland, TX 79701

(915) 687 5955

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

1650 FNL, 1980 FEL  
Sec 35, T19S, R33E

5. Lease Designation and Serial No.  
NM 9824

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Laguna Deep Ut. Fed #1

9. API Well No.

30-025-25886

10. Field and Pool, or Exploratory Area

East Gem Morrow (Gas)

11. County or Parish, State

Lea County, NM

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☒ Notice of Intent  
☐ Subsequent Report  
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment  
☒ Recompletion P.B.  
☐ Plugging Back  
☐ Casing Repair  
☐ Altering Casing  
☐ Other \_\_\_\_\_
- ☐ Change of Plans  
☐ New Construction  
☐ Non-Routine Fracturing  
☐ Water Shut-Off  
☐ Conversion to Injection  
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

MIRU PU (estimate start date - 6/22/98)

POH w/tbg

Set CIBP @ 12,900' w/35' of cmt on top

Run CBL

Spot acid

\* { Perforate Wolfcamp 11,279-284, 11,291-306'

Swab test. If prod. Place on production.

Set CIBP @ 11,200'

Spot acid.

Perforate Bonespring from 9319-27, 9352-58, 9423-31, 9437-41, 9454-59,

Swab Test

Frac if necessary

Place on production.

\* 6/19/98 call to Russ Mathis: the test of the W.C. is for evaluation purposes, the main goal is the Bone Sp. If W.C. is found to have enough production they may stop there. f. W.C.

1998 JUN -8 P 3:12  
RECEIVED  
BUREAU OF LAND MANAGEMENT  
ALBUQUERQUE, NEW MEXICO

14. I hereby certify that the foregoing is true and correct

Signed

Russ Mathis

Title

Russ Mathis - Production Manager

Date

06/02/98

(This space for Federal or State office use)

Approved by

Conditions of approval, if any:

Title

Date

APPROVED  
PETER W. COOPER  
JUN 19 1998  
BUREAU OF LAND MANAGEMENT  
ROSWELL, NEW MEXICO

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

\*See Instruction on Reverse Side