

3. TIH W/OE'D WS TO 7050' OR 50' INSIDE CSG STUB. SPOT 60 SX CLASS "C" CMT+ 2% CACL2, FROM 7050-6835'. PLUG #2:(6835-7050'). CSG STUB. PUH TO 5000'. SD WOC. TIH & TAG. RE-SPOT IF LOWER THAN 6900'.
4. PUH TO 5250'. SPOT 80 SX CLASS "C" CMT + 2% CACL2 FROM 5250-4938'. PLUG #3:(4938-5250'). SHOE PLUG. PUH TO 4600'. SD WOC. TIH & TAG. RE-SPOT IF LOWER THAN 5100'.
5. PUH TO 3305'. SPOT 85 SX CLASS "C" CMT FROM 3305'-2969'. PLUG #4:(2969-3305'). YATES & BASE SALT PLUG.
6. PUH TO 1930'. SPOT 50 SX CLASS "C" CMT FROM 1930-1730'. PLUG #5:(1730-1930'). TOP SALT PLUG.
7. PUH TO 450'. SPOT 120 SX CLASS "C" CMT FROM 450-SURF. PLUG #6:(SURF-450'). SURF SHOE & GRND WTR. POH.
8. ND BOP. RD MO DD PU. CUT OFF WH TO 3' BGL. WO PA PLATE & MARKER. CLEAN AND LEVEL LOCATION.