			. •			Form approx	ad	
Form 9-331 (May 1963)	ι	JNI'J STATES	105	BMIT IN TRIPLI	u re-		au No. 42-R1424.	
(.May 1966)	DEPARTMENT OF THE INTERIOR (Other Instructions of				1	5. LEASE DESIGNATION AND SERIAL NO.		
	GEOLOGICAL SURVEY					NM 6869 6. IF INDIAN, ALLOTTEE OR TRIBE NAME		
	UNDRY NOT	CES AND REPOR	rts on WI	ELLS	0. 14	Indian, Abborre		
(Do not use	this form for proposa	ils to drill or to deepen or	plug back to a (lifferent reservoir.				
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT_" for such proposals.)						7. UNIT AGREEMENT NAME		
WELL WELL OTHER 2. NAME OF OPERATOR						ARM OR LEASE NAD		
General Exploration Company						ipe Line De	ep Unit	
3. ADDRESS OF OPERATOR						ELL NO.		
4219 Sigma Road, Dallas, Texas 75240 . 4. LOCATION OF WELL (Report location clearly and in accordance with any Statement reference of the first statement of the statement of th						FIELD AND POOL, C)R WILDCAT	
See also space 17 below.)						Undesignated		
At surface 1970						11. SEC., T., E., M., OR BLK. AND SURVEY OR ABEA		
660' FSL and 1900' FWL DEC 8 ISTO 14. PERMIT NO. 15. ELEVATIONS (Show whether DF. 3. GEOLOGICAL SURVEY 3,782' GL HOBBS, NEW MEXICO								
000 .02 4				NOGICAL SUR		COUNTY OF PARIS	9-S, R-34-E	
14. PERMIT NO.		15. ELEVATIONS (Show wh	ether or. 3. Cit	S. NEW MEXIC		ea	New Mexico	
							<u></u>	
16.	Check Ap	propriate Box To Indi	cate Nature ol	Notice, Report	, or Other	Data		
	NOTICE OF INTEN	TION TO:		٤	SUBSEQUENT F	EPORT OF:		
TEST WATER S		PULL OR ALTER CASING	₩	ATER SHUT-OFF		REPAIRING	WELL	
FRACTURE TRE	I .	AULTIPLE COMPLETE	FI	RACTURE TREATMENT	r	ALTERING ([——]	
SHOOT OR ACI		ABANDON*	-	HOOTING OR ACIDIZI		report		
REPAIR WELL		HANGE PLANS	- ((Other) <u> </u>	mognity of mi	ultiple completion Report and Log f	on Well	
(Other)		RATIONS (Clearly state all ; mally drilled, give subsurfs				diam actimated de	to of starting any	
17. DESCRIBE PROPO proposed wo nent to this y	IL WEIL IS direction	RATIONS (Clearly state all) mally drilled, give subsurfs	ace locations and	measured and true	e vertical dep	ths for all marke	rs and zones perci-	
12-02-78:	TD 9 12 4601	logging and wi	re line te	sting. For	mation s	hale. Mud	- 10.5.	
12-02-70.	TD @ 13,450' logging and wire line testing. Formatio Vis 49. PV - 20. YP - 13. Gells - 3/10. PH - 9 film. Chlorides - 183,000. Totco @ 13,450' was 1 3/					WL - 4.4	. FC -	
	film Chlor	183 - 183 - 100	Dotco 0	13.450' was	1 3/4 a	legree.		
12-03-78:	TD @ 13,450'	laying down dr	ill pipe.	Formation	snale.	Mud - 10.5	. VIS	
	49. PV - 20. YP - 13. Gells - $3/10$. PH - 9.5. WL - 4.4. FC - film. Chlorides - 180,000.							
12-04-78:	TD 0 12 460	- running 5 1/2"	casing.	Formation s	hale. M	1ud - 10.4.	Vis	
12-04-70.	49. PV - 20). YP - 13. Ge	11s - 3/10	. PH - 9.5	. WL -	4.6. FC -	film.	
	Chlorides - 180,000. Rigging down. Ran 330 joints (13,472.02'), 5 1/2",							
12-05-78:	Rigging dowr	ı. Ran 330 join	ts (13,472	.02'), 5 1/	2", 1/#/	(11, 1) = 13	and 5-95, Ang' KB	
	LT & C and E	Buttress casing htralizers on jo	set at 13,	450° KB. F		8.9.10.	11. 94.	
	OF and OF	Companied with 1	500 sacks	Class "H" c	ement W1	τη 8/10% F	ididu 22,	
	95 and 96. Cemented with 1500 sacks Class "H" cemen 5/10% CFR-2 and 5# KCL per sack. (First 1200 sacks					20 di 15.0#	yga i tun	
	and last 300 sacks mixed at 16#/gallon). Pumped 500 head of cement. Pumped plug down with mud. Plug do					i ions mua i	iusn a-	
	1 1 . 6	w+ Dumpod nlu	a down wit	h mud Plu	a aown a	11. 1:30 0.0	1 12-4-	
	79 Rumpad	nlug with 1700	nsi, Floa	ts neia U.N	. run	recurns wi		
		et slips and rel	eased rig	at 7:00 p.m	1., 12-4-	-70.		
12-06-78:	Waiting on o	compretion.						
		- house and somest						
18. I hereby certi	fy that the foregoing i		Agent		n sicil	DATE 12-0)6-78	
SIGNED	ant to	TACKSTIT		TOTED F	1. 1			
(This space f	or Federal or State of	fice use)		COLL IL-	1073	ADD -		
		TIT	LE	1-0-0		ADATE		
APPROVED 1 CONDITIONS	OF APPROVAL, IF					(
				5 ¹		-		
		±0	D					

*See Instructions on Reverse Side