

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-26231
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1334
7. Lease Name or Unit Agreement Name	EAST VACUUM GB/SA UNIT TRACT 3308
8. Well No.	003
9. Pool name or Wildcat	VACUUM GB/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3936' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79762

4. Well Location
Unit Letter C : 1150 Feet From The NORTH Line and 1510 Feet From The WEST Line
Section 33 Township 17-S Range 35-E NMPM LEA County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: SULFATE SCALE/ACIDIZE ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5/24/95 MIRU DA&S DDU #192, KILL WELL, NUBOPE, COOH W/SUB, TIH W/SAND PUMP, TAG @ 4790', GISH W/KILL STRING, SISD.
5/25/95 KILL WELL, COOH W/KILL STRING, TIH W/CSG SCRAPER, TAG @ 4790, CLEAN OUT TO 4797', COOH, GIH W/PKR & TBG, SET PKR @ 4330', LOAD & TEST TO 500#, O.K., MIRU CHARGER, PUMP SCALE CONVERTER, RDMO CHARGER, SISD.
5/26/95 OPEN WELL, RECOVER 54 BBLS, RU SWAB, SWAB 30 BBLS, RD SWAB, MIRU HES, PUMP 4500 GALS 15% FERCHECK ACID, 2000# ROCK SALT IN 20 BBLS X-LINKED GELLED BRINE & 40 BBLS WATER. RDMO HES, SISD.
5/27-28-29/95 CREW OFF.
5/30/95 OPEN WELL FLOW BACK 97 BW & 77 BO, SISD.
5/31/95 PUMP SCALE SQZ, RELEASE PKR, COOH, GIH W/SUB PUMP, ND BOPE, FLANGE UP WELLHEAD, RD DDU, PUMP 14 HRS, NO TEST (OVER)

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE M. Sanders TITLE REGULATION SPECIALIST DATE 6/19/95

TYPE OR PRINT NAME M. SANDERS TELEPHONE NO. 915/368-1488

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

JUN 26 1995

6/01/95 PUMP 24 HRS, NO TEST.
6/02/95 PUMP 24 HRS, NO TEST, TEMP. DROP FROM REPORT.
6/13/95 TEST 121 BOPD, 189 BWPD, 214.5 MCF 38.1% CO2.
6/14/95 TEST 119 BOPD, 187 BWPD, 216.1 MCF 35.6% CO2.
6/15/95 TEST 118 BOPD, 184 BWPD, 215.2 MCF 33.8% CO2.
COMPLETE DROP FROM REPORT

RECEIVED
JUN 15 1995
OFFICE