

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. OG-4886
7. Unit Agreement Name ---
8. Farm or Lease Name Wainona State
9. Well No. 2
10. Field and Pool, or Wildcat Quail Queen
12. County Lea

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL <input checked="" type="checkbox"/>	GAS WELL <input type="checkbox"/>	OTHER <input type="checkbox"/>
Name of Operator Read & Stevens, Inc.		
Address of Operator P. O. Box 1518, Roswell, NM 88201		
Location of Well UNIT LETTER H 1980 FEET FROM THE North LINE AND 660 FEET FROM East LINE, SECTION 11 TOWNSHIP 19-S RANGE 34-E N.M.P.M.		

15. Elevation (Show whether DF, RT, GR, etc.) 3966.5' GR - 3977' RKB



Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	Remove Bridge Plug to test all perfs. <input checked="" type="checkbox"/>

6. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

On 10-12-79, from perfs. 5036' - 5046' and 5066' - 5073' pumped 27 BO & no water. Still lack 495 bbls. load water to recover. Pulled rods and pump. Washed 15' of sand off of retrievable bridge plug @ 5170'. Pulled tubg. and bridge plug. Ran 182 joints 2 3/8", EUE, 8 rd., 4.5#, J-55 tubing, total of 5732', set @ 5742' RKB with seating nipple @ 5708'. Ran rods and 2" x 1 1/2" x 16' RWBC pump. Started pumping from all perfs. 5036' - 5046', 5066' - 5073', 5530' - 5536', 5558' - 5588', 5608' - 5626', 5654' - 5662', 5664' - 5672' and 5704' - 5742'.

7. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE Agent	DATE 10-22-79
APPROVED BY 	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY: Dist 1, Supr		OCT 25 1979

RECEIVED
OCT 24 1977
O.C.D. HOBBS, OFFICE