

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-26388
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	B-1838-1
7. Lease Name or Unit Agreement Name	East Vacuum Gb/SA Unit Tract 3236
8. Well No.	005
9. Pool name or Wildcat	Vacuum Gb/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3969.8' GR	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook Street, Odessa, TX 79762

4. Well Location
Unit Letter E : 1203 Feet From The West Line and 1491 Feet From The North Line

Section 32 Township 17-S Range 35-E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Repair casing and acidize <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Last Test 03-16-91: 114 BOPD, 126 BWPD, 29.5 MCF.
04-28-91: RU DDU. Kill well. COOH w/submersible equipment. Found hole in 7" production casing 6' underground. Cut off 7" and 13-3/8" casing and repped to surface and recemented. Test annulus to 500#; ok. Acidize w/6000 gals 15% NEFE containing clay stabilizer and 5% 425; drop 5500# rock salt. ISIP: 2100#; Max. Press. 2450#. Swab. Squeeze for scale w/4 drums of 756 in 40 bbls 2% KCl. GIH w/tubing and submersible. Hang on; rig down. Pump 112 BOPD, 261 BWPD, 51 MCF. Job complete.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Reg. & Proration Supv. DATE 05-02-91

TYPE OR PRINT NAME L. M. Sanders

TELEPHONE NO. 368-1387

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: