

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-26395
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-1495
7. Lease Name or Unit Agreement Name East Vacuum Gb/SA Unit Tract 2622
8. Well No. 004
9. Pool name or Wildcat Vacuum Gb/SA

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE 'APPLICATION FOR PERMIT' (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Water Injection	
2. Name of Operator Phillips Petroleum Company	
3. Address of Operator 4001 Penbrook Street, Odessa, Texas 79762	
4. Well Location Unit Letter F : 2496 Feet From The North Line and 1544 Feet From The West Line Section 26 Township 17-5 Range 35-E NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3916' GR	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Perforate additional San Andres Pay <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

WIH with bit & 2-7/8" workstring, clean out hole to 475'. COOH with bit, made a trip with scraper.

Perforate 5-1/2" casing w/4" guns, 23 gram charges, 2 SPF, 4402'-4409', 4453'-4458', 4586'-4594', 4668'-4672', 4675'-4687', Total 72 holes. GIH w/5-1/2" pkr on 132 jts of 2-7/8" tbg. Set packer @ 4185' & tested to 500# OK.

Acidize w/5,200 gal of chic acid w/clay stabilizer & 4,500 lbs of rock salt as diverter in gelled brine. COOH L.D. W.S. & Pkr. S.D., GIH w/5-1/2" Set packer w/CO2 elements, 134 jts 2-7/8" J-55 tk 70 tbg. Tested tbg to 5000#. Set packer @ 4209' in 20 pts compression. Pumped 668 BBl @ 90#, Complete Drop from Report.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L.M. Sanders TITLE Supervisor Reg/Proration DATE 11-25-91

TYPE OR PRINT NAME L.M. Sanders TELEPHONE NO. 368-1488

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: