

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-26522
5. Indicate Type of Lease STATE ☒ FEE ☐
6. State Oil & Gas Lease No. B-2519
7. Lease Name or Unit Agreement Name E.Vac.GB/SA Unit Tr.3467
8. Well No. 001
9. Pool name or Wildcat Vacuum Gb/San Andres

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Phillips Petroleum Company
3. Address of Operator 4001 Penbrook, Odessa, Texas 79762	4. Well Location Unit Letter B : 1050 Feet From The North Line and 1520 Feet From The East Line Section 34 Township 17-S Range 35-E NMPM Lea County 10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3943' RKB 3929' GL

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Reactivation ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

10-8-90: Pumped 30 bbls. brine down tubing. Installed BOP and began pulling tubing.
10-9-90: CIBP @ 4512'. Drill CIBP @ 4512' & clean out to 4565'. Began drlg. CIBP #2 @ 4565'.
10-10-90: Cont drlg CIBP @ 4565' to 4567'. Clean out to 4738'. POOH and GIH w/ 4-3/4" bit and csg scraper to 4738'.
10-11-90: GIH w/RTTS pkr & set @ 4380'. Test csg to 500 psi, OK. Rig Up & stimulate well w/7000 gals 15% NEFe w/clay stab.& LST. Follow w/3000# rock salt. Max psi: 1800#; Min psi: 900#; Average: 1700 psi. ISIP: 1300.
10-12-90: Swab.
10-15-90: GIH w/2-7/8" tbg as follows: 1 jt, 1-2-1/4" X 23' pump barrel, 4 jts, 5-1/2" X 2-1/2" TA & 140 jts of 2-7/8" tbg. Pump set @ 4571'. ND BOP.
10-17-90: Down 24 hrs. Waiting on electricity.

-over-

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Reg. & Proration Supv. DATE 10-24-90
TYPE OR PRINT NAME L. M. Sanders TELEPHONE NO. 915-368-1488

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY:

10-18-90: Hook up electricity.
10-22-90: Pump 24 hrs. 0 BOPD, 474 BWP, 3 MCF, CO₂ 32.7%. Job
Complete.

OCT 26 1990