W Cortto Occireto	1	
DISTRIBUTION		
SANTA FE		
FILE		
V.1.0.1.		
LAND OFFICE	1	
OPERATOR		

## UIL CUMBERVATION DIVISION P. O. BOX 2088

Form C-183 Revised 10-1-78

BANTAFE	SANTA FE, NEW	MEXICO 87501	
71.8			Sa. Indicate Type of Lease
U.S.G.S.			State X Fee
OPERATOR			5. State Otl & Gas Lease No.
	API	No. 30-025- 26526	B-2181
SUNDRY	Y NOTICES AND REPORTS ON	IACK TO A DIFFERENT RESERVOIM.	7, Unit Agreement Name
• • • • • •			East Vacuum Gb/SA Unit
were Lyd were LJ	OTHER.		8. Form or Lease Name
. Name of Operator			East Vacuum Gb/SA Unit
Phillips Petroleum Com	npany		9. Well No. Tract 2648
Address of Operator	Odeses Towns 79762		001
4001 Penbrook Street,	odessa, lexas 17702		10. Field and Pool, or Wildcat
N 13	380 reet from the west	1310	Vacuum Gb/SA
UMIT LETTER	FEET FROM THE		
aguth	on	-S 35-E	
THE SOULIE LINE, SECTION			
THIRITIES.	15. Elevation (Show whethe	DF, RT, GR, etc.)	12. County
	3919.6'GR		Lea
Check	Appropriate Box To Indicate	Nature of Notice, Report	or Other Data
	TENTION TO:		UENT REPORT OF:
•		.	
PERFORM REMEDIAL WORK	PLUE AND ASANDON	REMEDIAL WORK	ALTERING CASING
TEMPORABILY ASAMSON		COMMENCE DRILLING OPHS.	PLUS AND ASANOSHMENT
PULL OR ALTER CASING	CHANGE PLANS	CASING TEST AND CEMENT JOB	isolate lower perfs X
		Set CIDE TO	isolate lower perfs X
OTHER			
The cribe Proposed or Completed Of	perations (Clearly state all pertinent de		cluding estimated date of starting any proposed
7. Describe Proposed or Completed Of work) SEE RULE 1 103.	parations (Clearly state all pertinent de		cluding estimated date of starting any proposed
7-23-86: 4750' PTD	RU DDU, installed BOP, W	IH w/gauge ring, tagg	ed TD at 4678'.
7-23-86: 4750' PTD		IH w/gauge ring, tagg	ed TD at 4678'.
7-23-86: 4750' PTD COOH & WIH v	RU DDU, installed BOP, W	IH w/gauge ring, tagg	ed TD at 4678'. 550'.
7-23-86: 4750' PTD COOH & WIH v	RU DDU, installed BOP, With CIBP, tagged fluid a	IH w/gauge ring, tagg	ed TD at 4678'. 550'.
7-23-86: 4750' PTD COOH & WIH v 7-24-86: WIH w/4406' 7-25-86: Pmpd 24 hrs.	RU DDU, installed BOP, With CIBP, tagged fluid a	IIH w/gauge ring, tagget 150', set CIBP at 4	ed TD at 4678'. 550'.
7-23-86: 4750' PTD COOH & WIH w/4406' 7-25-86: Pmpd 24 hrs.	RU DDU, installed BOP, With CIBP, tagged fluid a of 2-7/8" tbg & centril, w/no gauge rec 21 BO, 682 BW, 2 MC	IIH w/gauge ring, tagget 150', set CIBP at 4	ed TD at 4678'. 550'.
7-23-86: 4750' PTD COOH & WIH w 7-24-86: WIH w/4406' 7-25-86: Pmpd 24 hrs: 7-26-86: Pmpd 24 hrs: 7-27-86: Pmpd 24 hrs: 7-28 thru	RU DDU, installed BOP, With CIBP, tagged fluid a of 2-7/8" tbg & centril, w/no gauge rec 21 BO, 682 BW, 2 MC, no gauge.	III w/gauge ring, tagget 150', set CIBP at 4 ift pump. Pmpd 12 hr	ed TD at 4678'. 550'.
7-23-86: 4750' PTD COOH & WIH w 7-24-86: WIH w/4406' 7-25-86: Pmpd 24 hrs: 7-26-86: Pmpd 24 hrs: 7-27-86: Pmpd 24 hrs: 7-28 thru	RU DDU, installed BOP, With CIBP, tagged fluid a of 2-7/8" tbg & centril, w/no gauge rec 21 BO, 682 BW, 2 MC	III w/gauge ring, tagget 150', set CIBP at 4 ift pump. Pmpd 12 hr	ed TD at 4678'. 550'.
7-23-86: 4750' PTD COOH & WIH w 7-24-86: WIH w/4406' 7-25-86: Pmpd 24 hrs: 7-26-86: Pmpd 24 hrs: 7-27-86: Pmpd 24 hrs: 7-28 thru 7-29-86: Pmpd 48 hrs:	RU DDU, installed BOP, With CIBP, tagged fluid a of 2-7/8" tbg & centril, w/no gauge rec 21 BO, 682 BW, 2 MC, no gauge.	III w/gauge ring, tagget 150', set CIBP at 4 ift pump. Pmpd 12 hr	ed TD at 4678'. 550'.
7-23-86: 4750' PTD COOH & WIH w 7-24-86: WIH w/4406' 7-25-86: Pmpd 24 hrs: 7-26-86: Pmpd 24 hrs: 7-27-86: Pmpd 24 hrs: 7-28 thru 7-29-86: Pmpd 48 hrs: 7-30 thru	RU DDU, installed BOP, With CIBP, tagged fluid a of 2-7/8" tbg & centril, w/no gauge.  , rec 21 BO, 682 BW, 2 MC, no gauge.  , 41 BO, 1343 BW, 3 MCFG.	III w/gauge ring, tagget 150', set CIBP at 4 ift pump. Pmpd 12 hr	ed TD at 4678'. 550'.
7-23-86: 4750' PTD COOH & WIH w 7-24-86: WIH w/4406' 7-25-86: Pmpd 24 hrs: 7-26-86: Pmpd 24 hrs: 7-27-86: Pmpd 24 hrs: 7-28 thru 7-29-86: Pmpd 48 hrs: 7-30 thru 9-04-86: Pmpd 24 hrs	RU DDU, installed BOP, With CIBP, tagged fluid a of 2-7/8" tbg & centril, w/no gauge.  , rec 21 BO, 682 BW, 2 MO, no gauge.  , 41 BO, 1343 BW, 3 MCFG.  a day, no gauge.	TH w/gauge ring, tagg t 150', set CIBP at 4 ift pump. Pmpd 12 hr	ed TD at 4678'. 550'.
7-23-86: 4750' PTD COOH & WIH w 7-24-86: WIH w/4406' 7-25-86: Pmpd 24 hrs: 7-26-86: Pmpd 24 hrs: 7-27-86: Pmpd 24 hrs: 7-28 thru 7-29-86: Pmpd 48 hrs: 7-30 thru 9-04-86: Pmpd 24 hrs	RU DDU, installed BOP, With CIBP, tagged fluid a of 2-7/8" tbg & centril, w/no gauge.  , rec 21 BO, 682 BW, 2 MC, no gauge.  , 41 BO, 1343 BW, 3 MCFG.  a day, no gauge.  , 22 BO, 461 BW, 1 MCFG,	TH w/gauge ring, tagg t 150', set CIBP at 4 ift pump. Pmpd 12 hr	ed TD at 4678'. 550'.
7-23-86: 4750' PTD COOH & WIH w 7-24-86: WIH w/4406' 7-25-86: Pmpd 24 hrs: 7-26-86: Pmpd 24 hrs: 7-27-86: Pmpd 24 hrs: 7-28 thru 7-29-86: Pmpd 48 hrs: 7-30 thru 9-04-86: Pmpd 24 hrs 9-05-86: Pmpd 24 hrs Job complete	RU DDU, installed BOP, With CIBP, tagged fluid a of 2-7/8" tbg & centril, w/no gauge.  The rec 21 BO, 682 BW, 2 MC, no gauge.  Al BO, 1343 BW, 3 MCFG.  a day, no gauge.  22 BO, 461 BW, 1 MCFG, e.	TH w/gauge ring, tagg t 150', set CIBP at 4 ift pump. Pmpd 12 hr	ed TD at 4678'. 550'.
7-23-86: 4750' PTD COOH & WIH w 7-24-86: WIH w/4406' 7-25-86: Pmpd 24 hrs: 7-26-86: Pmpd 24 hrs: 7-27-86: Pmpd 24 hrs: 7-28 thru 7-29-86: Pmpd 48 hrs: 7-30 thru 9-04-86: Pmpd 24 hrs 9-05-86: Pmpd 24 hrs Job complete	RU DDU, installed BOP, With CIBP, tagged fluid a of 2-7/8" tbg & centril, w/no gauge.  , rec 21 BO, 682 BW, 2 MC, no gauge.  , 41 BO, 1343 BW, 3 MCFG.  a day, no gauge.  , 22 BO, 461 BW, 1 MCFG,	TH w/gauge ring, tagg t 150', set CIBP at 4 ift pump. Pmpd 12 hr	ed TD at 4678'. 550'.
7-23-86: 4750' PTD COOH & WIH w 7-24-86: WIH w/4406' 7-25-86: Pmpd 24 hrs: 7-26-86: Pmpd 24 hrs: 7-27-86: Pmpd 24 hrs: 7-28 thru 7-29-86: Pmpd 48 hrs: 7-30 thru 9-04-86: Pmpd 24 hrs 9-05-86: Pmpd 24 hrs Job complete	RU DDU, installed BOP, With CIBP, tagged fluid a of 2-7/8" tbg & centril, w/no gauge.  The rec 21 BO, 682 BW, 2 MC, no gauge.  Al BO, 1343 BW, 3 MCFG.  A day, no gauge.  A day, no gauge.  B day, no gauge.  A day, no gauge.	TH w/gauge ring, tagg t 150', set CIBP at 4 ift pump. Pmpd 12 hr	ed TD at 4678'. 550'. s, no test.
7-23-86: 4750' PTD COOH & WIH w 7-24-86: WIH w/4406' 7-25-86: Pmpd 24 hrs: 7-26-86: Pmpd 24 hrs: 7-27-86: Pmpd 24 hrs: 7-28 thru 7-29-86: Pmpd 48 hrs: 7-30 thru 9-04-86: Pmpd 24 hrs 9-05-86: Pmpd 24 hrs Job complete	RU DDU, installed BOP, With CIBP, tagged fluid a of 2-7/8" tbg & centril, w/no gauge.  The rec 21 BO, 682 BW, 2 MC, no gauge.  Al BO, 1343 BW, 3 MCFG.  A day, no gauge.  A day, no gauge.  B day, no gauge.  A day, no gauge.	TH w/gauge ring, tagget 150', set CIBP at 4. ift pump. Pmpd 12 hr	ed TD at 4678'. 550'. s, no test.
7-23-86: 4750' PTD COOH & WIH w 7-24-86: WIH w/4406' 7-25-86: Pmpd 24 hrs: 7-26-86: Pmpd 24 hrs: 7-27-86: Pmpd 24 hrs: 7-28 thru 7-29-86: Pmpd 48 hrs: 7-30 thru 9-04-86: Pmpd 24 hrs Job complete	RU DDU, installed BOP, With CIBP, tagged fluid a of 2-7/8" tbg & centril, w/no gauge.  The rec 21 BO, 682 BW, 2 MC, no gauge.  Al BO, 1343 BW, 3 MCFG.  A day, no gauge.  A day, no gauge.  B day, no gauge.  A day, no gauge.	TH w/gauge ring, tagget 150', set CIBP at 4. ift pump. Pmpd 12 hr	ed TD at 4678'. 550'. s, no test.