

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
L-5316

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Sol West III	8. Farm or Lease Name Shearn West
3. Address of Operator P. O. Box 10151, El Paso, Texas 79992	9. Well No. 1
4. Location of Well UNIT LETTER J 1980 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 3 TOWNSHIP 17-S RANGE 35-E NMPM.	10. Field and Pool, or Wildcat So. Shoe Bar (Morrow)
15. Elevation (Show whether DF, RT, GR, etc.) 3,959.7' GL 3,975.7' KB	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER Progress Report (Completion) <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 4-05-80: Swabbed an estimated 16 BLW and acid residue with little gas. Lowered fluid level from 6000' to 10,400'. Swabbed an additional 10 BLW and acid residue lowering fluid level to 11,800'. Shut in.
- 4-06-80: Swabbed an estimated 10 BLW and acid residue lowering fluid level from 9500' to 12,000'. Shut in.
- 4-07-80: Shut down for Sunday.
- 4-08-80: Swabbed an estimated 14 BLW and acid residue with traces of distillate. Lowered fluid level from 8000' to 12,000'. Stuck swab on last run.
- 4-09-80: Swabbed 2 1/2 barrels very dirty load water and acid residue with traces of distillate. Released packer. Circulated 75 barrels 3% KCL. Tried to catch fish. Shut down.
- 4-10-80: Caught fish. Cut off sand line. Pulled 90 stands of tubing and recovered bar and sand line cutter. Shut down.
- 4-11-80: Respliced sand line. Retrieved bridge plug at 12,410' and reset at 10,207'. Pulled up to 10,100'. Shut down.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Patty Robbins TITLE Agent DATE 4/11/80

APPROVED BY _____ TITLE _____ DATE APR 11 1980

CONDITIONS OF APPROVAL, IF ANY: _____