

Procedure cont: Mid-America State #2
Intent to P&A

- 6.) POH W/WS TO 600'. SPOT 30 SX. CL.'C' CMT. PLUG FROM 600' TO 489'.
- 7.) POH W/WS TO 15'. SPOT 3 SX CL.'C' CMT PLUG FROM 15' TO 4' BGL POH W/WS.
- 8.) RD. CUT OFF CSG. 4' BGL. WELD ON STEEL PLATE AND DRY HOLE MARKER. RECLAIM LOCATION . RR.

NOTE: *NOTIFY NMO&GCC 24 HRS PRIOR TO BEGINNING OPERATIONS.
***ALL CALCS. BASED ON USE OF CL. 'C' CMT., W/A YIELD OF 1.32 FT3/SK.**
***DISPLACE ALL PLUG W/9.5 PPG MUD LAIDEN FLUID.**
