

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

5. Lease Designation and Serial No.
NM-14789-A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation
8910180420

8. Well Name and No.

YOUNG DEEP UNIT # 1

9. API Well No.

30-025-26640

10. Field and Pool, or Exploratory Area
YOUNG WOLFCAMP

11. County or Parish, State
LEA COUNTY, NM

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir
Use "APPLICATION FOR PERMIT..." for such proposals

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Harvey E. Yates Company

3. Address and Telephone No.

P.O. Box 1993, Roswell, NM 88202 1-505-623-6601

4. Location of Well (Footage, Sec., T., R., M, or Survey Description)

UNIT LETTER D, 660' FNL & 660' FWL
SEC. 10, T-18S, R-32E

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

TYPE OF ACTION

☐ Notice of Intent

☒ Subsequent Report

☐ Final Abandonment

☐ Abandonment

☐ Recompletion

☐ Plugging Back

☒ Casing Repair

☐ Altering Casing

☒ Other

CLEAN PERF PLUGGED
DUE TO DRILLING MUD

☐ Change in Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log Form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled,
give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)

PROBLEM: DEVELOPED A HOLE IN THE CASING AT 6147'.
SET CIBP @ 10,380' TO PROTECT WOLFCAMP PERFS.
11-23-95 RAN CASING INSPECTION LOG. (POSS. HOLES @ 6147 & 6026'). CHECKED
WITH PACKER. FOUND HOLE @ 6147'.
PUMPED 100' CMT PLUG @ 8037' TO PROTECT PREVIOUS SQUEEZED PERFS.
11-30-95 SET CMT RET. @ 5980' & CMT'D 5 1/2" CASING ANNULUS w/ 660 SKS 35/65 POZ
AND 200 SKS CL "H".
DRLD OUT CMT RET. AND CMT PLUGS. CIRC HOLE CLEAN. DRLD OUT CIBP @ 10,380'
& PUSHED TO PBTD OF 10,653'.
12-12-95 ACDZ PLUGGED PERFS w/ 3000 GALS 15% NEFE.
12-14-95 JETTED WOLFCAMP PERFS w/ WATER & ACID TO CLEAN UP DRILLING MUD
DAMAGE.
12-16-95 PUT BACK ON PUMP.

14. I hereby certify that the foregoing is true and correct

Signed

Ray F. Nokes

RAY F. NOKES

Title

PROD. MGR./ ENG.

Date 1/2/96

(This space for Federal or State office use)

Approved by

Title

Date

J. Lira

Conditions of approval, if any: