

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-26684
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2273-2
7. Lease Name or Unit Agreement Name East Vacuum Gb/SA Unit Tract 3456
8. Well No. 008
9. Pool name or Wildcat Vacuum Gb/SA
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3929' GR

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER

2. Name of Operator
Phillips Petroleum Company

3. Address of Operator
4001 Penbrook St. Odessa, Texas 79762

4. Well Location
Unit Letter C : 250 Feet From The North Line and 2500 Feet From The West Line

Section 34 Township 17-S Range 35-E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: Clean out & acidized ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

6/12/92 MIRU DDU, NU BOP COOH w/tbg & sub equip. Pump 20 bbl 2% KCL w/10 gal TW 425, spot 1/2 of 2 drums & 110 gal 2% KCL out of tbg. Set pkr @ ±4347' Load & test ok wait 3 hrs displace rest of chemical.
6/15/92 RU Swab, MIRU charger to pump 3000 gal 15% NEFE HCL acid.
6/16-6/17/92 RU Swab.
6/18/92 RU Swab. MIRU charger to pump 5 drums TH 756 in 50 bbls 2% KCL, displace w/200 bbl 2% KCL w/5 gals TC 420 in first 100 bbls. RDMO Charger.
6/19/92 MIRU kill truck, unset pkr. Kill well COOH w/pkr. PU GIH w/sub equip & tbg. ND BOP flange up well head. Start pumping. RDMO DDU.
6/23/92 Pump 24 hrs. test 113 BOPD, 454 BWPD, 208.4 MCF, & 1837.742 GOR.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE L. M. Sanders TITLE Supervisor, Reg. & Pro. DATE 7/1/92

TYPE OR PRINT NAME L. M. Sanders

TELEPHONE NO. 915/368-1488

(This space for State Use) ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

JUL 06 '92

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: