

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

G.L. CONSERVATION DIVISION

P. O. BOX 2088

SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF EST. RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State ☒	Fee ☐
5. State Oil & Gas Lease No.	
63373	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO OPEN OR PLUG UP TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐		7. Unit Agreement Name
2. Name of Operator Gulf Oil Corporation		8. Form or Lease Name Lea "ED" State (NCT-A)
3. Address of Operator P. O. Box 670, Hobbs, NM 88240		9. Well No. 4
4. Location of Well UNIT LETTER <u>K</u> , <u>2230</u> FEET FROM THE <u>South</u> LINE AND <u>2200</u> FEET FROM THE <u>West</u> LINE, SECTION <u>16</u> TOWNSHIP <u>19S</u> RANGE <u>34E</u> N.M.P.M.		10. Field and Pool, or Wildcat Quail Ridge Bone Springs
15. Elevation (Show whether T.F., RT, GR, etc.) 3774' GL		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☐	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OPNS. ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOB ☐	OTHER ☒ Perfd, Aczd

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Perf 10,112'-10,120' with (2) ½" o-phase decentralized burrless JHPF (16 holes). Spot 20% NEFE inhibited HCL 10,120'-10,050'. Respot 20% acid over perf 10,112'-10,120'. Perf 10,110'-10,122' with (1) ½" o-phase decentralized JHPF (13 holes). Swabbed. Pump 750 gals 20% NEFE & 39 bbls flush down tubing. Tag bottom of fill at 10,112', reverse out fill to 10,130'. Spot 20% NEFE acid to bottom of tubing at 10,050'. Acidize down 2-7/8" tubing with 6000 gals gelled pad & 6000 gals 20% NEFE slick HCL. Pump at 10 BPM, 5500# up to 7000#, acid on spot from 7000# back to 4600#. ISIP 2000#, 3 min well on vac. RIH with 2-3/8" tubing with tapped BPOB, x-over, bottom tubing at 10,113', SN at 10,076'. RIH with pump with gas anchor & rods; spaced pump out & clamped rod off. Changed pump & RIH with rods & pump. Hang well on. Complete after drilling perfring & acidizing 10-19-80.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>R.D. Pitzer</u>	TITLE <u>Area Engineer</u>	DATE <u>10-21-80</u>
APPROVED BY <u>[Signature]</u>	TITLE <u>[Signature]</u>	DATE <u>[Signature]</u>
CONDITIONS OF APPROVAL, IF ANY:		