

Submit 3 Copies
to Appropriate
District Office.

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. <u>30-025-26773</u>
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2317
7. Lease Name or Unit Agreement Name Hale State
8. Well No. 1-Y
9. Pool name or Wildcat Midway Strawn

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	
2. Name of Operator Barbara Fasken	
3. Address of Operator 303 W. Wall, Suite 1900, Midland, TX 79701-5116	
4. Well Location Unit Letter <u>J</u> : <u>2260</u> Feet From The <u>South</u> Line and <u>1650</u> Feet From The <u>East</u> Line Section <u>8</u> Township <u>17-S</u> Range <u>37-E</u> NMPM <u>Lea</u> County <u></u>	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3796' RKB	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Plugback from Devonian to Strawn <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Set 5½" CIBP at 10,950' and capped with 2 sx cement. (Devonian below plug). 6-7-93.
2. Perforated Strawn at 10,705'-10,771' with 1-11/16" strip gun with 48 holes. 6-9-93.
3. Acidized Strawn with 2500 gals. 15% NEFE acid. Used 100 ball sealers for diversion. 6-11-93.
4. Swabbed well to clean up. 6/11-12/93.
5. POW with tubing and packer. RIW with rod pumping equipment. Set 640-365-144 pumping unit and started well pumping. 6/14-16/93.
6. Well tested 156 BO + 0 BW, 432 mcfpd. 6-19-93.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Jimmy Davis Jr TITLE Drig. & Oprns. Sup't. DATE 6-21-93
TYPE OR PRINT NAME Jimmy Davis, Jr. TELEPHONE NO. 915-687-17

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE JUN 22 1993

CONDITIONS OF APPROVAL, IF ANY:

SWC

2A
Midway Strawn