

**EAST VACUUM GRAYBURG SAN ANDRES UNIT
ATTACHMENT XII TO FORM C-108
APPLICATION FOR AUTHORIZATION TO SOLVENT**

STATEMENT OF HYDRAULIC INTEGRITY

Phillips Petroleum Company has examined available geological data and finds no evidence of open faults nor any other hydraulic connection between the injection zone and any underground source of drinking water.