STATE OF NEW MEXICO ENERGY AND MINERALS DEPARTMENT

We. er tonice acceives					
DISTRIBUTION					
SANTA PE					
FILE					
U.S.G.S.					
LAND OFFICE					
OPERATOR		1			

OIL CONSERVATION DIVISION

DISTRIBUTION	•	P. O. BOX 2088 Revised 10			
SANTAPE		SANTA FE, NEW	MEXICO 87501	WE41366 10-1-70	
FILE]		Sa. Indicate Type of Lease	
U.S.G.S.]		State X Fee	
LAND OFFICE					
OPERATOR		<u> </u>		5, State Oll & Gun Lease No.	
		_	API NO. 30-025-26991	B-2131	
	SUNDE	RY NOTICES AND REPORTS ON	WELLS		
(DO NOT USE THI	S FORM FOR PRO	OPOSALS TO DRILL ON TO DEEPLH OR PLUG B.	ALR TO A DIFFERENT RESERVOIR.		
	USC "APPEICAT	IGH FOR PLRMIT (FORM C-101) FOR SUC	H PROPOSALS.	7, Unit Agreement Name	
1. OIL [X]	GAS				
WELL X	weil	OTHER-		East Vacuum Gb/SA Unit	
2. Name of Operator				8. Form or Lease Name Fact Vacuum Ch/SA Unit	
Phillips Petroleum Company				East Vacuum Gb/SA Unit, Tract 2648	
J. Address of Operator				9. Well No.	
	Ol Donbar	not St. Odogga Towns /	0.762	002	
	OI Pelibro	ook St., Odessa, Texas /	7702	10. Field and Pool, or Wildcat	
4. Location of Well				·	
UNIT LETTER	3	25 FEET FROM THE South	LINE AND 1300 FEET FRE	Vacuum Gb/SA	
West		26 TOWNSHIP 17-S	35-E		
THE	LINE, SECTI	ON TOWNSHIP	NANGENMP	(
mmm	mm	15. Elevation (Show whether	DF. RT. GR. etc.)	12. County	
		((((()			
771111111111111111111111111111111111111	7777777	3921.4 RKB, 391	0.9 GL	Lea	
16,	Check	Appropriate Box To Indicate N	lature of Notice, Report or C	Other Data	
NC		NTENTION TO:	-	NT REPORT OF:	
•		PLUG AND ABANDON			
PERFORM REMEDIAL WORK	` 	PLUG AND ABANDON		ALTERING CASING	
TEMPORARILY ASAHDON		· .	COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT	
PULL OR ALTER CASING		CHANGE PLANS	CASING TEST AND CEMENT JOB X		
			othem Total depth	X	
OTHER					
<u></u>					
		perations (Clearly state all pertinent deta	vils, and give pertinent dates, includi	ng estimated date of starting any proposed	
work) SEE RULE 11	03.				
11-22-80 MI Cactus Drlg. Spud w/12-1/4" bit to 356'. Ran 8-5/8", 24#, K-55 csg set					
	at 353'	. Cmtd w/400 sxs CJ. "H"	w/2% CaCl ₂ . Circd 60 s	sxs cmt to surface.	
	Tstd cs	g 12 hrs after plug down.	Temp of cmt 650, form	mation temp in zone	
		t strength at time of csg			
		hrs. Tstd csg and BOP 1			
	CCSC 12	mrs. Ista esg and bor i	ooon, ok. Dila ancaa	w, , , , o bic.	
12 1 00	D-11 4-	4900 mp			
12-1-80	Drld to 4800 TD. Attempted to log, no success.				
12-2-80	12-2-80 Ran 5-1/2", 15.5#, K-55 csg set at 4800'. Cmtd w/1100 sxs TLW w/12#/sx				
	salt, fo	ollowed w/400 sxs Cl "H"	w/5#/sx salt. Displace	ed plug w/10% Acetic	
		d FW. Bmpd plug w/200# p			
12-3-80	Polesco	d rigprep to complete.			
12 3 00	RC1Ca5C	a rig prep to comprete.			
. ~					
18. I hereby certify that	the information	s shove is true and complete to the best of	of my knowledge and belief.		
11/2/	20				
	Telli-	W. J. Mueller TITLE Sr	. Engineering Spec.	12-22-80	
elento V	Car- ca-	- " O' HOCTICE THE DI		VAIL	
1 dist	<u> </u>			_	
Orig.	Signed by			DEC	
APPROVED BYLes	Clements	TITLE		DATE BLU WAY	
CONDITIONS OF DIPE	Sat-Illandar	¹a			
	F. •				