

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

SUBMIT IN TRIPLI
(Other instructions on
reverse side)

Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>		5. LEASE DESIGNATION AND SERIAL NO. NM-67110
2. NAME OF OPERATOR Manzano Oil Corporation 505/623-1996		6. IF INDIAN, ALLOTTEE OR TRIBE NAME
3. ADDRESS OF OPERATOR P.O. Box 571, Roswell, NM 88202		7. UNIT AGREEMENT NAME
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 1980' FNL & 660' FEL of Section 31		8. FARM OR LEASE NAME Federal "31-G"
14. PERMIT NO. 30-025-27131		9. WELL NO. 1
15. ELEVATIONS (Show whether BV, RT, OR, etc.) 3574.38' GR		10. FIELD AND POOL, OR WILDCAT Wildcat
		11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 31, T19S, R33E
		12. COUNTY OR PARISH Lea
		13. STATE NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

12/27/86 thru See previous Sundry Notice dated 1/14/87.

1/8/87

1/9/87 Ran tbg to 7644' & drilled to 7654'. Circulated up iron cuttings, circulated clean.

thru Ran magnet on sandline & recovered cones off bit, drilled to 7654' & fell thru at

1/11/87 7882'. Circ clean.

1/12/87 Tagged plug @ 10,737', drilled to 10,841'. Circ clean, tagged up @ 11,554 & drilled

-1/13/87 to PBTD 11,564'. Circ clean & test casing to 1000#, held OK. Rigged down reverse

unit.

1/14/87 Perforated Wolfcamp 11,434-450' w/17 holes & Bone Spring 10,500-540' w/40 holes.

thru Set packer @ 11,373' & acidized Wolfcamp zone w/2500 gal 20% NEFE acid & 34 ball

1/20/87 sealers. Flowed & tested @ 10,413'.

1/21/87 Set Lock-set bridge plug @ 10,639' & packer. Tested to 1000#, held OK.

thru Acidized Bone Spring w/1500 gallons 20% NEFE acid & 60 ball sealers. Flowed &

1/26/87 tested Bone Spring.

1/27/87 Fraced w/30,000 gal 40# gel, 70 tons (393 bbl) CO2 and 650 sks 20/40 sand.

thru Swabbed, flowed & tested Bone Spring formation.

ACCEPTED FOR RECORD

3/16/87 Potential well @ 15 BOPD, 0 BWPD & Gas 12 MCFGPD

MAR 25 1987

G

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Jackie Midkiff/Prod. Clerk

DATE

CARLSBAD, NEW MEXICO

3/16/87

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side