				M. OIL CONS. COMMENSION AND AND AND AND AND AND AND AND AND AN		
Form 3160-5		FED STATES		Budget Bureau No. 1004-0135		
(June 1990)		T OF THE INTERIOR		Expires: March 31, 1993		
	BUREAU OF L	AND MANAGEMENT		5. Lease Designation and Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS			NM-16350-A			
De not use this form	sundry notices n for proposals to dri	ll or to deepen or reentry to a	different reservoir	6. If Indian, Allotte or Tribe Name		
Do not use this fort	"ADDI ICATION RC	R PERMIT" for such propos	sals			
		T IN TRIPLICATE		7. If Unit or CA, Agreement Designation		
	SUDIVIL			8910180420		
1. Type of Well	well X Other	WIW				
			8. Well Name and No.			
2. Nume of Operator Harvey E. Yates Company			YOUNG DEEP UNIT # 5			
			9. API Well No.			
				30-025-27336		
3. Address and Telephone No.		00000 1 505 603 6601		10. Field and Pool, or Exploratory Area		
P.O. Box 1993	, Roswell, NNI a	8202 1-505-623-6601		YOUNG BONE SPRING, N		
		hattan)		11. County or Parish, State		
4. Location of Well (Footage, Se 1980' FEL & 660'		ipriod)		LEA CO., NM		
B, SEC. 10, T-18S,						
,						
CHECK ADDDC	PRIATE BOY (e) T	O INDICATE NATURE OF	NOTICE, REPORT	, OR OTHER DATA		
TYPE OF SUBMI	SSION	1	YPE OF ACTION			
			Change in	n Plans		
Notice of Intent	Abandonment		· ⊢-{	struction		
	Recompletion		Non-Rou	Non-Routine Fracturing		
X Subsequent Report	Plugging Bac Casing Repair		Water Sh	Water Shut-Off		
The state of the sector sector	11		Conversion to Injection			
	I I Altering Cast	ng	Conversi	on to injection		
Finai Abandoment	Altering Casi	ng ACIDIZE & TESTING	Conversi Dispose	-		
Finai Abandoment	Altering Casi X Other	ACIDIZE & TESTING CASING & PACKER	Dispose	-		
	XOther	ACIDIZE & TESTING CASING & PACKER	Dispose V (Note: Report m Completion or f	Water esuits of multiple completion on Well Recompletion Report and Log Form.)		
13. Describe Proposed of Completed C give subsurface locations	X Other Operations (Clearly state all partiase and measured and true vertical de	ACIDIZE & TESTING	Dispose 1 (Note: Report re Completion or F nuted date of starting any proposed wo rk.)	Water esuits of multiple completion on Well Recompletion Report and Log Form.)		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP	X Other Sperations (Clearly state all pertise and measured and true vertical de ED 750 GALS 15% H	ACIDIZE & TESTING CASING & PACKER out details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI	Dispose 1 (Note: Report or Completion or f mated date of starting any proposed wo rk.) ON PERFS.	Water esuits of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drifted,		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP	X Other Sperations (Clearly state all pertise and measured and true vertical de ED 750 GALS 15% H	ACIDIZE & TESTING CASING & PACKER ont details, and give pertinent dates, including esth pute for all markers and zones pertment to this we	Dispose 1 (Note: Report or Completion or f mated date of starting any proposed wo rk.) ON PERFS.	Water esuits of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drifted,		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP	X Other Sperations (Clearly state all pertise and measured and true vertical de ED 750 GALS 15% H	ACIDIZE & TESTING CASING & PACKER out details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI	Dispose 1 (Note: Report or Completion or f mated date of starting any proposed wo rk.) ON PERFS.	Water ssuits of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drifted,		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP	X Other Sperations (Clearly state all pertise and measured and true vertical de ED 750 GALS 15% H	ACIDIZE & TESTING CASING & PACKER out details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI	Dispose 1 (Note: Report or Completion or f mated date of starting any proposed wo rk.) ON PERFS.	Water esuits of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drifted,		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP	X Other Sperations (Clearly state all pertise and measured and true vertical de ED 750 GALS 15% H	ACIDIZE & TESTING CASING & PACKER out details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI	Dispose 1 (Note: Report or Completion or f mated date of starting any proposed wo rk.) ON PERFS.	Water ssuits of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drifted, RT.		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP	X Other Sperations (Clearly state all pertise and measured and true vertical de ED 750 GALS 15% H	ACIDIZE & TESTING CASING & PACKER out details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI	Dispose 1 (Note: Report or Completion or f mated date of starting any proposed wo rk.) ON PERFS.	Water soulds of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drilled, RT.		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP	X Other Sperations (Clearly state all pertise and measured and true vertical de ED 750 GALS 15% H	ACIDIZE & TESTING CASING & PACKER out details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI	Dispose 1 (Note: Report or Completion or f mated date of starting any proposed wo rk.) ON PERFS.	Water soulds of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drilled, RT.		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP	X Other Sperations (Clearly state all pertise and measured and true vertical de ED 750 GALS 15% H	ACIDIZE & TESTING CASING & PACKER out details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI	Dispose (Note: Report re Completion or F nuted date of starting any proposed wo rk.) ON PERFS. EE ATTACHED CHAI	Water soulds of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drilled, RT.		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP	X Other Sperations (Clearly state all pertise and measured and true vertical de ED 750 GALS 15% H	ACIDIZE & TESTING CASING & PACKER out details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI	Dispose 1 (Note: Report or Completion or f mated date of starting any proposed wo rk.) ON PERFS.	Water soulds of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drilled, RT.		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP	X Other Sperations (Clearly state all pertise and measured and true vertical de ED 750 GALS 15% H	ACIDIZE & TESTING CASING & PACKER and details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI # FOR 15 MINS. HELD OK. S	Dispose (Note: Report of Completion of F mated date of starting any proposed wo rk.) ON PERFS. EE ATTACHED CHAI	Water souts of multiple completion on Well Recompision Report and Log Form) rk. If well is directionally drilled, RT.		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP	X Other Sperations (Clearly state all pertise and measured and true vertical de ED 750 GALS 15% H	ACIDIZE & TESTING CASING & PACKER and details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI # FOR 15 MINS. HELD OK. S	Dispose (Note: Report re Completion or F nuted date of starting any proposed wo rk.) ON PERFS. EE ATTACHED CHAI	Water souts of multiple completion on Well Recompision Report and Log Form) rk. If well is directionally drilled, RT.		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP 11-1-94 TEST (X Other perations (Clearly state all pertaw and measured and true vertical de ED 750 GALS 15% H CSG & PKR TO 5504	ACIDIZE & TESTING CASING & PACKER and details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI # FOR 15 MINS. HELD OK. S	Dispose (Note: Report of Completion of F mated date of starting any proposed work.) ON PERFS. EE ATTACHED CHAI	Water souts of multiple completion on Well Recompision Report and Log Form) rk. If well is directionally drilled, RT.		
13. Describe Proposed of Completed C give subsurface locations 11-1-94 PUMP 11-1-94 TEST (14. 1 hereby certify their the for	X Other Peerations (Clearly state all pertise and measured and true vertical des ED 750 GALS 15% H CSG & PKR TO 5504 cSG is true and correct	ACIDIZE & TESTING CASING & PACKER and details, and give pertinent dates, including estin puts for all markers and zones pertinent to this wo HCL TO CLEAN UP INJECTI # FOR 15 MINS. HELD OK. S	Dispose (Note: Report of Completion of F mated date of starting any proposed work.) ON PERFS. EE ATTACHED CHAI	Water souts of multiple completion on Well Recompision Report and Log Form) rk. If well is directionally drilled, RT.		
13. Describe Proposed of Completed (give subsurface locations 11-1-94 PUMP 11-1-94 TEST (X Other perations (Clearly state all pertus and measured and true vertical de ED 750 GALS 15% H CSG & PKR TO 550 CSG & PKR TO 550 setting is true and corpect	ACIDIZE & TESTING CASING & PACKER and details, and give pertinent dates, including estin pute for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI # FOR 15 MINS. HELD OK. S	Dispose (Note: Report of Completion of F nated date of starting any proposed we rk.) ON PERFS. EE ATTACHED CHAI NOV 1 5 199 CARLSBAD, NEW 1	Water soulds of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drilled, RT. Control in the structure of the s		
13. Describe Proposed of Completed C give subsurface locations 11-1-94 PUMP 11-1-94 TEST (14. 1 hereby certify that the for Signed Cary f. (This space for Federal (X Other perations (Clearly state all pertus and measured and true vertical de ED 750 GALS 15% H CSG & PKR TO 550 CSG & PKR TO 550 setting is true and corpect	ACIDIZE & TESTING CASING & PACKER and details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI # FOR 15 MINS. HELD OK. S # FOR 15 MINS. HELD OK. S	Dispose (Note: Report of Completion of F nated date of starting any proposed we rk.) ON PERFS. EE ATTACHED CHAI NOV 1 5 199 CARLSBAD, NEW 1	Water soulds of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drilled, RT. Control in the structure of the s		
13. Describe Proposed of Completed C give subsurface locations 11-1-94 PUMP 11-1-94 TEST (14. I hereby certify that the for Signed Carp ((This space for Federal Approved by	X Other perations (Clearly state all pertus and measured and true vertical des ED 750 GALS 15% H CSG & PKR TO 550 construction of the second sec	ACIDIZE & TESTING CASING & PACKER and details, and give pertinent dates, including estin puts for all markers and zones pertinent to this wo HCL TO CLEAN UP INJECTI # FOR 15 MINS. HELD OK. S	Dispose (Note: Report of Completion of F nated date of starting any proposed we rk.) ON PERFS. EE ATTACHED CHAI NOV 1 5 199 CARLSBAD, NEW 1	Water sould of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drilled, RT. RT. Date 11/8/94		
13. Describe Proposed of Completed C give subsurface locations 11-1-94 PUMP 11-1-94 TEST (14. 1 hereby certify that the for Signed Cary f (This space for Federal (X Other perations (Clearly state all pertus and measured and true vertical des ED 750 GALS 15% H CSG & PKR TO 550 construction of the second sec	ACIDIZE & TESTING CASING & PACKER and details, and give pertinent dates, including estin puts for all markers and zones pertinent to this we HCL TO CLEAN UP INJECTI # FOR 15 MINS. HELD OK. S # FOR 15 MINS. HELD OK. S	Dispose (Note: Report of Completion of F nated date of starting any proposed we rk.) ON PERFS. EE ATTACHED CHAI NOV 1 5 199 CARLSBAD, NEW 1	Water sould of multiple completion on Well Recompletion Report and Log Form.) rk. If well is directionally drilled, RT. RT. Date 11/8/94		

