

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-27788

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☐ GAS WELL ☒ OTHER

2. Name of Operator
Nearburg Producing Company

3. Address of Operator
419 W. Cain, Hobbs, NM 88240

4. Well Location
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line
Section 2 Township 17-S Range 35-E NMPM Lea County

7. Lease Name or Unit Agreement Name

New Mexico CX State

8. Well No.
2

9. Pool name or Wildcat
Shoe Bar Meadow Morrae

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 1) Set 5½ CIBP @ 12410' cap W/35' cement
- 2) Load hole with mud
- 3) Spot 25 sacks cement, plug @ 10324'
- 4) Spot 25 sacks cement, plug @ 7600'
- 5) Spot 25 sacks cement, plug @ 5066'
- 6) Cut 5½ casing @ 2770', pull out of hole
- 7) Spot 50 sacks cement, plug @ 5½ stub 2820', W.O.C., Tag cement top @ 2618'
- 8) Cut 8-5/8 casing @ 550', pull out of hole
- 9) Spot 135 sacks cement, plug @ 600' 8-5/8 stub & 13-3/8 shoe, W.O.C.
Tag cement top @ 454'
- 10) Spot 20 sacks cement, plug @ surface and set PA marker
- 11) Job completed 12-6-96

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Elrica K. Kleck TITLE District Secretary DATE 12/09/96
TYPE OR PRINT NAME Elrica K. Kleck TELEPHONE NO. 915-683-5321

(This space for State Use)

APPROVED BY Johnny Robinson TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY TC