

Submit 3 Copies
To Appropriate
District Office
DISTRICT I
1625 N. French Dr., Hobbs, NM 88240

DISTRICT II
811 South First, Artesia NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

State of New Mexico
Energy, Minerals and Natural Resources Department

OIL CONSERVATION DIVISION

2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS)	
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>	WELL API NO. 30-025-27794
2. Name of Operator POLLUTION CONTROL INC.	5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator P.O. BOX 2158, HOBBS, NM 88241	6. State Oil & Gas Lease No. LG 1339
4. Well Location Unit letter <u>L</u> : <u>1650</u> feet from the <u>SOUTH</u> line and <u>333</u> feet from the <u>West</u> line Section <u>32</u> Township <u>175</u> Range <u>36E</u> NMPM Lea County	7. Lease Name or Unit Agreement Name: EXXON ST.
8. Well No. 1	
9. Pool name or Wildcat VACUUM GRAYBURG	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3865-8 G.R.	

Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	
OTHER: <input type="checkbox"/>		OTHER: <input type="checkbox"/>	

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

MIRU 4/7/00 1. Plug @ 4900' 4 1/2 CIBP w/10 sacks on top. 2. Perforate and Squeeze 1950' w/40 sacks WOC & TAG 1840' 3. 35 sacks @ 4 1/2 stub @ 1000', 35 sacks 1050' WOC & TAG TOC 930' 4. 50 sacks @460' WOC & TAG TOC 340', 10 sacks surface, install dry hole marker, RDMO 4/13/00

10 lb Brine Mud between all plugs

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE W. L. Alderman TITLE Cementer

Type or print name

(This space for State use)

APPROVED BY Ed Gonzalez

Conditions of approval, if any:

TITLE Field Rep

DATE 4-24-03

GW

