

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION

P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. L1634	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name Humble City Unit
2. Name of Operator Bass Enterprises Production Co.		8. Farm or Lease Name Humble City Unit
3. Address of Operator P. O. Box 2760, Midland, Texas 79702-2760		9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>990</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>36</u> TOWNSHIP <u>17S</u> RANGE <u>37E</u> N.M.P.M.		10. Field and Pool, or Whicat Hobbs Channel (San Andres)
15. Elevation (Show whether DF, RT, GR, etc.) 3716' KB		12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.)

12-27-83

Rig up Carr Well Service. Pull rods, pump & tbq. Shut down 12-28-83 due to bad weather.

12-29-83 RIH & set 5½" CIBP @ 7,010, POOH & RD wireline. RIH & Prep to cement CIBP, shut down for night.

12-30-83

Spotted 5 sx cement on top of CIBP @ 7,010'. POOH, RIH w/string shot & shot 5½" csg @ 4825' prep to POOH.

12-31-83

LD 117 cts 5½" 17# csg & 20' cut off. RIH w/tbg to top of csg stub. Stung into csg & RIH to 4,875' spotted 100' (35sx) cement plug, pulled up & shut down for Sunday 1-1-84.

1-2-84

Tagged top of cement plug @ 4,790'. Pulled up to 2,360', spotted 100' (50sx) cement plug. Lay down tbq. & spot 10 sx cement plug @ surface. Install dry hole marker & fill cellar well P & A.

1-2-84

Tony Plattsmier with State of New Mexico witnessed job & approved.  
Final Report.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED R. C. Spoutchens TITLE Sr. Production Clerk DATE 1-4-84

OIL & GAS INSPECTOR

APPROVED BY David Catanach TITLE \_\_\_\_\_ DATE APR 2 1984

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED  
JAN 9 1984  
O.C.D.  
HOBBS OFFICE