

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION  
P.O. Box 2088  
Santa Fe, New Mexico 87504-2088

|   |
|---|
| WELL API NO.<br>30-025-27803  |
| 5. Indicate Type of Lease<br>STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/> |
| 6. State Oil & Gas Lease No.<br>LG-607  |

|   |   |
|---|---|
| <b>SUNDRY NOTICES AND REPORTS ON WELLS</b><br>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)                 |   |
| 1. Type of Well:<br>OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>   | 7. Lease Name or Unit Agreement Name<br><br>Bass 32 State |
| 2. Name of Operator<br>Bass Enterprises Production Co.  |   |
| 3. Address of Operator<br>P.O. Box 2760 Midland, Texas 79702-2760   | 8. Well No.<br>1  |
| 4. Well Location<br>Unit Letter <u>C</u> : <u>660</u> Feet From The <u>North</u> Line and <u>1980</u> Feet From The <u>West</u> Line<br>Section <u>32</u> Township <u>19S</u> Range <u>34E</u> NMPM <u>Lea</u> County <u></u> | 9. Pool name or Wildcat<br>Apache Ridge Bone Spring       |
| 10. Elevation (Show whether DF, RKB, RT, GR, etc.)<br>3658.2' GL, 3676' KB  |   |

|   |   |
|---|---|
| 11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data |   |
| <b>NOTICE OF INTENTION TO:</b>  | <b>SUBSEQUENT REPORT OF:</b>                                |
| PERFORM REMEDIAL WORK <input type="checkbox"/>                                | REMEDIAL WORK <input type="checkbox"/>                      |
| TEMPORARILY ABANDON <input type="checkbox"/>                                  | ALTERING CASING <input type="checkbox"/>                    |
| PULL OR ALTER CASING <input type="checkbox"/>                                 | COMMENCE DRILLING OPNS. <input type="checkbox"/>            |
| OTHER: <input type="checkbox"/>   | PLUG AND ABANDONMENT <input type="checkbox"/>               |
|   | CASING TEST AND CEMENT JOB <input type="checkbox"/>         |
|   | OTHER: <u>Plug Back</u> <input checked="" type="checkbox"/> |

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

9-18-91 RIH and set 5 1/2" CIBP at 12,995' Pressure 5 1/2" CSG. to 1000# OK. RIH and dump 35' Cement on CIBP at 12,995'.

9-24-91 RIH with 5 1/2" model "K" CMT. retainer to 10,154' Circ. and set retainer at 10,154'. Pumped 400 SX Class "H" Cement w/ additives CIRL 15 SX to surface, WOC.

9-25-91 Ran Tem. Survey TOC at 7990' POOH. RIH w/3 3/8" CSG. Gun loaded 2 JSPF at 1800 phased. w/16 GR GOEX charges Perf interval 10,106' - 10,126' (41 holes).

9-26-91 Acidized Perfs. 10,106' - 10,126' Bone Spring with 5,000 Gals. 15% HCI with additives, and 60 1.1 SG Ball Sealers.

9-27-91 Swab & Clean up well

9-28-91 Swab & Clean out ball Sealers

10-2-91 RIH and set 5 1/2" CIBP at 10,010' Dump 35' class "H" cement, test Csg. to 1000 PSI. OK.

10-3-91 Perf 9480' - 9544' w/ 214 shots, Swab & SDON. Prep. to frac.

10-14-91 Frac Bone Spring Perf 9480'-9544' with 30,000 Gals. Hyborgel 40 plus with additives.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE R.C. Houtchens TITLE Sr. Production Clerk DATE 11-7-91 OVER

TYPE OR PRINT NAME R.C. Houtchens

TELEPHONE NO. (915) 683-2277

(This space for State Use)  
ORIGINAL SIGNED BY JERRY SEXTON  
DISTRICT I SUPERVISOR

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY:

NOV 16 1991

3A Quail Ridge Marrow

CONT.

and 72,000# resin coated 20/40 sand. Clean up well & swab prep to test woo.

NOV 12 1991

HOBBS OVER