

Submit 3 Copies To Appropriate District
Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 South First, Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-27947
1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEB <input type="checkbox"/>
2. Name of Operator Western Oil Producers		6. State Oil & Gas Lease No. LG-740
3. Address of Operator P O Box 1498 Roswell, NM 88202		7. Lease Name or Unit Agreement Name: State MTS
4. Well Location Unit Letter <u>0</u> : <u>554</u> feet from the <u>South</u> line and <u>2,086</u> feet from the <u>East</u> line Section <u>4</u> Township <u>19S</u> Range <u>35E</u> NMPM County <u>Lea</u>		8. Well No. <u>1</u>
10. Elevation (Show whether DR, RKB, RT, GR, etc.)		9. Pool name or Wildcat Scharb Bone Springs

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input checked="" type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER: <input type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

13 3/8" csg set at 310' Cement Circ.
8 5/8" csg set at 3,865' Cement Circ.
5 1/2" csg set at 10,774' 4,500 sks CL "H"

6-3-94 MIRU
6-4-94 Set CIBP 9,500 w/35' cement on top.
6-5-94 Tag cem plug 9,460' set CIBP 7,200' w/35' cement on top.
6-6-94 Cut 5 1/2" csg and pull same at 6,500' w/50' cem plug in pipe
and 50' cem outside (45 sks)
6-7-94 Set 100' plug 3,800 to 3,900', 50 sx
Set 100' plug 1,800 to 1,900', 70 sx
Set 100' plug 275 to 325', 70 sx
Set 10 sx at surface
Installed dry hole marker, Cleaned Location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Genny Long TITLE Production Analyst DATE 9-1-00
Type or print name Genny Long Telephone No. 505-623-5070
(This space for State use)

APPROVED BY Johnny Robinson TITLE _____ DATE _____
Conditions of approval, if any:

JC

8

