

## DISTRICT I

1625 N. French Dr., Hobbs, NM 88240

## DISTRICT II

811 S. First Street, Artesia, NM 88210

## DISTRICT III

1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 South Pacheco  
Santa Fe, New Mexico 87505WELL API NO.  
30-025-27988

5. Indicate Type of Lease

STATE ☐FEE ☐X ☒

6. State Oil &amp; Gas Lease No.

7. Lease Name or Unit Agreement Name

SNYDER RANCH

8. Well No.

1

9. Pool Name or Wildcat

BRUSHY CANYON

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A  
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"  
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL

GAS

WELL ☒WELL ☐

OTHER

Name of Operator

ELK OIL COMPANY

3. Address of Operator

POST OFFICE BOX 310, ROSWELL, NEW MEXICO 88202-0310

4. Well Location

Unit Letter

H

1980

Feet From The

NORTH

Line and

660

Feet From The

EAST

Line

Section

8

Township

19 SOUTH

Range

35 EAST

NMPM

LEA

County

10. Elevation (Show whether DF, RKE, RT, GR, etc.)

3862' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐PLUG AND ABANDON ☒TEMPORARILY ABANDON ☐CHANGE PLANS ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETION ☐OTHER ☐

## SUBSEQUENT REPORT OF:


REMEDIAL WORK ☐ALTERING CASING ☐COMMENCE DRILLING OPNS. ☐PLUG AND ABANDONMENT ☐CASING TEST AND CEMENT JOB ☐OTHER ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work)

SEE RULE 1103 For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

Propose to plug and abandon well as follows:

- (1) Set CIBP with 35' cement at 5075'.
- (2) Set 100' plug inside 5 1/2 at 4192' (8 5/8 shoe plug), 50 in / 50 out.
- (3) Set 100' plug inside 5 1/2 at 1800', top of Salt.
- (4) Set 100' plug inside 5 1/2 at 507' (13 3/8 shoe plug), 50 in / 50 out.
- (5) 10 sxs surface plug.
- (6) Mud between all plugs.
- (7) Install dry hole 4' X 4' marker.



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

TITLE

PRESIDENT

DATE

2/3/03

TYPE OR PRINT NAME

JOSEPH J. KELLY

TELEPHONE NO.

505-623-3190

(This space for State Use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

ORIGINAL SIGNED BY

GARY WLEWINK

OC FIELD REPRESENTATIVE / STAFF MANAGER

FEB 04 2003

DATE