

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. A-4096	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT - 1" (FDAM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		7. Unit Agreement Name
2. Name of Operator Exxon Corporation		8. Farm or Lease Name New Mexico 'DD' State
3. Address of Operator P.O. Box 1600, Midland, TX 79702		9. Well No. 4
4. Location of Well K 2080 South 1980 UNIT LETTER FEET FROM THE LINE AND FEET FROM West 4 19S 35E THE LINE, SECTION TOWNSHIP RANGE NMPM.		10. Field and Pool, or Wildcat Scharb Bone Spring
15. Elevation (Show whether DF, RT, GR, etc.) 3907'-GR		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐  
TEMPORARILY ABANDON ☒  
PULL OR ALTER CASING ☐  
OTHER ☐

PLUG AND ABANDON ☐  
CHANGE PLANS ☐  
OTHER ☐

REMEDIAL WORK ☐  
COMMENCE DRILLING OPNS. ☐  
CASING TEST AND CEMENT JOBS ☐  
OTHER ☐

ALTERING CASING ☐  
PLUG AND ABANDONMENT ☐  
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Install BOP's. POH with production equipment.
2. Make a gauge ring run if production equipment is scaled or paraffined upt.  
Make a bit run only if necessary.
3. RIH and set a CIBP 70' above top prforation.
4. Dump bail 35 feet of cement on CIBP.
5. RIH with production string and circulate well with inhibited freshwater containing 10 gals Corexit 7672 and 20 gals Corexit 7720 per 100 Bbls.
6. Pressure test CIBP and casing to 500#.
7. RIH with rods and RDMO.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Rosemarie Whitlock TITLE Office Assistant DATE 5/22/86

ORIGINAL SIGNED BY JERRY SEXTON  
APPROVED BY DISTRICT SUPERVISOR TITLE \_\_\_\_\_ DATE JUN 2 1986  
CONDITIONS OF APPROVAL, IF ANY: