

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.
30-025-28018

5. Indicate Type of Lease
STATE ☒ FEE ☐

6. State Oil & Gas Lease No.
H 4096

7. Lease Name or Unit Agreement Name
New Mexico "DD" State

8. Well No.
6

9. Pool name or Wildcat
Sahar b - Bone Springs

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator
J & G Enterprise Ltd Co.

3. Address of Operator
P.O. Box 100, Artesia, NM 88210

4. Well Location
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line
Section 4 Township 19S Range 35E NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)
3902 GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

13 3/4 Set @ 425' Cemented 350 SX-Circ.
9 5/8 Set @ 3998' Cemented 1970 SX-Circ.
5 1/2 Set @ 10798' Cemented 1400 SX-TOO 3385'
CIBP w/ 35' cement @ 10450
CIBP w/ 35' cement @ 9196
CIBP w/ 35' cement @ 8080

#1 Set 100' Plug @ 5000'
#2 Set 100' Plug @ shoe I @ 3998' Tag Plug
#3 Cut & Laydown 5 1/2" Casing @ 3300'
#4 Set 100' Stub Plug @ 3300' Tag Plug
#5 set 10 sx Surface Plug - Install Dry Hole Marker
100' ALWB 485-325
#6 Rig Down - Cut Anchors - Cover Pit - Clean Location

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

J T Jackson

TITLE

President

DATE

4-2-97

TYPE OR PRINT NAME

J T Jackson

TELEPHONE NO.

546-9680

(This space for State Use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

See Above

APR 04 1997

all copies deleted
except 100' stub plug
#29795 also RKB