

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-28053
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. B-2317
7. Lease Name or Unit Agreement Name Mable
8. Well No. 4
9. Pool name or Wildcat Vacuum Gb/SA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER Water Injection	7. Lease Name or Unit Agreement Name Mable
2. Name of Operator Phillips Petroleum Company	8. Well No. 4
3. Address of Operator 4001 Penbrook St., Odessa, Texas 79762	9. Pool name or Wildcat Vacuum Gb/SA

4. Well Location Unit Letter <u>E</u> : <u>1330</u> Feet From The <u>North</u> Line and <u>1310</u> Feet From The <u>West</u> Line Section <u>35</u> Township <u>17-S</u> Range <u>34-E</u> NMPM Lea County

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4014' GL; 4024' RKB

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Temp. Abandon <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7/16 MIRU. Install BOP & release and COOH w/packer and tubing.

7/19 GIH with 5-1/2" CIBP set at 4437'. Circ. casing with inhibited packer fluid close BOP and pressure test casing to 500# and record on circular chart. Held OK. COOH and lay down 2-7/8" injection tbq. TA well.

This Approval of Temporary
Abandonment Expires 8-1-99

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Alma Franco TITLE Supv., Reg. Affairs DATE 8/23/94
TYPE OR PRINT NAME L.M. Sanders TELEPHONE NO. 915/368-1488

(This space for Stamp Use)
STATE OF NEW MEXICO
OIL CONSERVATION DIVISION

SEP 06 1994

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

