

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 12-1

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.O.S.	
LAND OFFICE	
OPERATOR	

1. Indicate Type of Lease
State ☒ Fee ☐
2. State Oil & Gas Lease No.
LG 1016

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO REEVAL OR PUMP BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT TO DRILL OR TO REEVAL OR PUMP BACK TO A DIFFERENT RESERVOIR".)

1. OIL WELL ☐ GAS WELL ☒ OTHER ☐	7. Unit Agreement No.
2. Name of Operator Western Oil Producers, Inc.	8. Farm or Lease Name Union Texas State
3. Address of Operator Box 1498, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER A 660 FEET FROM THE North LINE AND 990 FEET FROM THE East LINE, SECTION 21 TOWNSHIP 17S RANGE 36E N.M.P.M.	10. Field and Pool, or Village W.C.
11. Elevation (Show whether L.F., R.T., G.L., etc.) 3854.72 G.L.	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐	PLUG AND ABANDON ☒	REMEDIAL WORK ☐	ALTERING CASING ☐
TEMPORARILY ABANDON ☐	CHANGE PLANS ☐	COMMENCE DRILLING OR REEVAL ☐	PLUG AND ABANDONMENT ☐
PULL OR ALTER CASING ☐	OTHER ☐	CASING TEST AND CEMENT JOBS ☐	
		OTHER ☐	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

2/11/83

T.D. 4410'
100' plug 4400'-4300' 40 sx
100' plug 3120'-3020' 40 sx
100' plug 2135'-2035' 40 sx
100' plug 412'-362' 40 sx
10 sx at surface

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Arnold Hewitt TITLE Agent DATE 2/22/83

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____

CONDITIONS OF APPROVAL, IF ANY:

FEB 24 1983