

STATE OF NEW MEXICO  
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION  
P. O. BOX 2088  
SANTA FE, NEW MEXICO 87501

Form C-103  
Revised 10-1-78

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Draco Energy, Inc.	8. Farm or Lease Name Carter Est. Estate
3. Address of Operator P.O. Box 11404, Midland, Texas 79702	9. Well No. 1
4. Location of Well UNIT LETTER N 1000 FEET FROM THE South LINE AND 1080 FEET FROM THE East LINE, SECTION 32 TOWNSHIP 17S RANGE 39E NMPM.	10. Field and Pool, or Wildcat Johnson Draw (Yeso)
15. Elevation (Show whether DF, RT, GR, etc.) 3636.5 GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:


PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set 25 sx from 6410-6223  
Cut off 5 1/2" casing @ approximately 5000'. — 106 PLUG 1/2 IN & 1/2 OUT OF ESC STOP  
Set 35 sx from 4525-4425 (8 5/8" set @ 4475')  
Set 35 sx @ 2065-1965  
Set 10 sx @ surface  
Cut off 8 5/8" & 13 3/8" 3 ft below ground level  
Install dry hole marker

RECEIVED 24  
MAY 1987  
OIL CONSERVATION DIVISION  
STATE OF NEW MEXICO

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 	TITLE V. President	DATE 3/17/87
APPROVED BY ORIGINAL SIGNED BY JERRY SEXTON DISTRICT I SUPERVISOR	TITLE	DATE MAY 13 1987
CONDITIONS OF APPROVAL, IF ANY:		

RECEIVED

MAR 18 1981

OCD

HOBBS OFFICE